feedback

table of contents

HANGAR NOISE	inside cover
FIXED WING	1
ROTORCRAFT	4
ENGINES	5
HEADS UP	6
SUSPECTED UNAPPROVED PARTS	6
EQUIPMENT ADs	7
FEATURE ARTICLE	8
FAA SAIBs	9
FAA UNAPPROVED PARTS (UPNs)	10
AME SYMPOSIA SCHEDULE	10
SDR LIST	11

hangar *noise*

A Message for Aircraft Maintenance Personnel

Amendment to CAR 591 Service Difficulty Reporting is now in effect

http://info.tc.gc.ca/CivilAviation/RegServ/Affairs/cars/Part5/591.htm

CAR 591 has recently been revised and published on the Transport Canada (TC) web site. The main changes are a result of Transport Canada's growth in the development of new requirements and the methodology in which TC is able to develop corrective action based on reported in-service defects, malfunction or failure of an aeronautical product, component, equipment or part. The changes further enhance the reporting system and better satisfy the requirements of Annex 8 to the Convention on International Civil Aviation (ICAO), Part II, Chapter 4, Section 4.3.8.

These changes affect Canadian aviation document holders listed below where the reporting of service difficulties to Transport Canada is mandatory. Voluntary reporting is strongly recommended for all other areas of civil aviation

The format used to present the regulatory structure has changed slightly. Most of the information previously found in Airworthiness Manual (AWM) 591 and Appendices A,B,C and D, have been moved to the new Advisory Circular 591 001.

Nous Farmed

Certificate Holders (amended 2004/12/01)	Pursuant to the following CARs
Flight Training Unit (Aeroplane & Helicopter)	406
Manufacturer of Aeronautical Products	561
Type Certificate holder	511
Modification and Repair Approval Holder (amended 2004	4/12/01) 513
Distributor of Aeronautical Products	563
Approved Maintenance Organization	573
Private Operator - Passenger Transportation	604
Air Operator (Commercial Air Service)	706

	Old Format	New Format
Regulation	CAR 591	CAR 591
Standard	AWM 591	AWM 591
Advisory Material	Appendices to the Standard	Advisory Circular 591-001

Old Farmet

More specifically, this amendment includes the following changes:

- + A definition of Service Difficulty Reporting and Unapproved Parts has been added to the requirement;
- + The reporting of Suspected Unapproved Parts (SUP) is now mandatory using the SDR system as the vehicle to report these issues. One SDR per event is required.
- + A list that specifies the minimum required information to be provided with the service difficulty report has been added.

For further information, please contact your local Transport Canada Center (TCC) or TC, Continuing Airworthiness in Ottawa.

http://www.tc.gc.ca/CivilAviation/certification/continuing/menu.htm

For more information or copies of feed back or other Civil Aviation publications, call 1 800 305-2059 or visit our Web site at www.tc.gc.ca/civilaviation/certification.

To ensure continued delivery, send any address changes to:

Transport Canada, Civil Aviation Communications Centre (AARC), Place de Ville, Ottawa, ON, K1A ON8.

Copyright - Minister of Public Works and Government Services, Canada, 2005
Permission is granted by the Department of Transport, Canada, to copy and/or reproduce the contents of this publication in whole or in part provided that full acknowledgement is given to the Department of Transport, Canada, and that the material be accurately reproduced. While use of this material has been authorized, the Department of Transport, Canada, shall not be responsible for the manner in which the information is presented, nor for any interpretations thereof.

The information in this publication may not be updated to reflect amendments made to original content. For up-to-date information, contact the Department of

Transport, Canada The information in this publication is to be considered solely as a guide and should not be quoted as or considered to be a legal authority. It may become obsolete in whole or in part at any time without notice.

Notice/Disclaimer:

Service Difficulty Reports (SDR) are normally published verbatim. Transport Canada assumes no responsibility for the accuracy or content of any of these reports. Only grammatical or spelling errors are corrected and content may be reduced as well as personal references deleted.

Cette publication est aussi disponible en français.

fixed wing

BEECH A100

SDR # 20040705001

Landing Gear Actuator Failure

With the aircraft on jacks and the landing gear swings completed, maintenance noted that the left landing gear doors were hanging open with the gear retracted. The actuator was removed with the suspicion that it had slipped internally, subsequently causing it to be out of sync with the nose and the right main gear actuators.

Inspection of the actuator after removal revealed the actuator having an excessive amount of internal resistance. The actuator was sent to the overhaul facility for further evaluation.

The submitter added that the overhaul facility had disassembled the actuator and discovered excessive wear and stripped threads on the nut, with scoring on the screw threads. The unit is being sent to Raytheon for further analysis.

The actuator only had 760 cycles since overhaul. These actuators are usually required to be overhauled every 7 500 cycles and the endplay checked every 1 000 cycles.

Elevator Torque Tube Pin

SDR # 20040608002

During the installation of a new elevator torque tube, P/N 1156100103, a technician noticed that one of the torque tube tapered pins was installed beyond the manufacturer's limits. The small end of the torque tube extended 0.125 inches beyond the surface of the support.

Maintenance Manual Chapter 27 30 00, page 202A, states "the small end of the taper pin body should extend .0000 to 0.060 inches beyond the surface of the support. If the dimensions are not met, new parts will be required."

The submitter stated that a second defective elevator torque tube was found in a similar condition from stores. A third torque tube from the same batch was also removed from company stores.

The defective elevator torque tubes were returned to the aircraft manufacturer for their action.

CESSNA 150M

SDR # 20040610010

SDR # 20040622006\

Corroded Fuel Line

A fuel smell was detected in the cockpit. An investigation revealed a fuel line, P/N 040031158, under the floor directly forward of the belly drain and downstream of the fuel shut-off valve, had developed a pinhole leak. This line passes through a bulkhead but became corroded and pitted in the area around the grommet.


Although the grommet was serviceable, in this case accumulation of water or dirt can be corrosive. Early detection can reduce downtime.

CESSNA 152

Stabilizer Assembly Cracked

During inspection the stabilizer assembly was found cracked in numerous places.

AME's are reminded to carefully inspect these areas that sometimes can be hard to detect.



CESSNA 172

Throttle Control Swaged Ends Worn

SDR # 20040621010

SDR # 20040628004

The crimped pivot end of the throttle control, P/N 2520851, was found loose during inspection. This part was replaced 160 hours before as a new part supplied from the manufacturer.

A second SDR reported that the swaged swivel joint on the throttle control was worn to the point where the ball end could be removed from its swaged socket with ease.

This defect was discovered during a routine inspection and is the second occurrence of such a defect noted by the same operator within the past few weeks. The part was returned to the manufacturer for evaluation.

AME's are reminded to carefully check these areas and always expect the unexpected. This part appears to have failed prematurely.

CESSNA 525

Bleed Air Coupling Worn


The pilot noticed a sharp increase in the inter-turbine temperature (ITT) when the power levers were advanced during the pre-flight run-up.

An inspection of the engine bleed air line couplings revealed a bleed air leak but did not reveal significant wear. On two occasions, the coupling, P/N W99124CE, failed to remain latched and the joint opened, once on the left engine and the second on the right engine.

The submitter added that this aircraft had been modified at the manufacturer to remove the flex coupling and tube arrangement bleed air systems, and then installed the new coupling and tube arrangement.


This upgraded arrangement has some inherent alignment difficulties and should be carefully inspected.

SDR # 20040624009



DE HAVILLAND DHC-6 300

Failed Rudder Bearing



SDR # 20040611008

A pilot discovered the rudder making a snapping noise while checking for freedom of movement and range for travel during the pre-flight walkaround. The lower attach bearing of the rudder had failed, allowing the rudder to rub on the attachment mount. The rudder was removed and the bearing replaced. The lower rudder attachment mount was inspected and no faults were found.

The rudder was re-installed, and the rudder, rudder trim and rudder gear tab rigging were all checked and determined serviceable.

Time Since New (TSN): 233 536 hours

Remember to determine the cause of any abnormality, however seemingly insignificant.

Some rectifications can wait and some cannot......

PIPER PA32RT 300T

Autopilot Cable Frayed

SDR # 20040811007

The pilot suspected the aft trim drum was malfunctioning because the stabilizer trim became stiff at colder temperatures. An inspection of the complete control system was carried out and revealed the cable, P/N 62701-135, was discovered to be 60% frayed over the area of the electric autopilot motor.

A new cable was installed with the specified correct tension and a system functional check was carried out.

The submitter suspects that low cable tension caused the cable to jam around the severed pulley windings near the trim motor.

A search in the SDR database revealed four similar occurrences. The autopilot trim motor is hidden from direct view under the aft edge of the cargo wall. Extra vigilance is required to properly inspect this area.

PIPER PA 42 720 -

SDR # 0040621003

Fire Detection Wiring Shorted

On approach for landing, the right engine fire warning light activated. The pilot deployed the engine fire bottle, secured the engine and declared an emergency. The landing was carried out uneventfully.

Maintenance inspected the engine and found no evidence of fire. The fire detection system was inspected and the three probes, P/Ns 5064200, were individually tested with the Megger test unit. Two of the three probes were found serviceable.

On the low 0-200 ohms range, the third probe showed a resistance of about 1 meg ohm when it should have been infinite or open. The engineer checked it at the 250v setting and the resistance dropped to basically nothing, indicating shorted or corroded contacts.

The faulty probe was replaced and circuit tests were carried out satisfactorily.

rotor craft

EUROCOPTER (AEROSPATIALE) AS 350BA ARRIEL 1B

SDR # 20040817002


Clogged Engine Bleed Valve

During flight, it was noted that compressor stalling would occur when crew increased the throttle settings. The crew then carried out a normal landing.

Maintenance personnel discovered that the microswitch for the bleed valve had come apart and the broken pieces of the roller had jammed between the plunger and the housing. This debris prevented proper opening and closing of the bleed valve "butterfly valve" which resulted in compressor stalling when engine power was increased. However, the butterfly valve was still opening enough for the cockpit light to indicate fully open.


EUROCOPTER (AEROSPATIALE) AS 350BA Blade Skin Cracked

SDR # 20040817003



While conducting a 100-hour inspection, a 5.50-inch (138mm) crack was discovered on the upper surface in Zone C on one main rotor blade. The crack was beyond the maintenance manufacturer's specified limit of 4.00 inch (100mm), which is applicable in this area.

This defect should be kept in mind when inspecting the main rotor blades.



BELL 206B

SDR # 20040708012

Engine Flame-out


During a maintenance ground run, the engine flamed out when the boost pumps were shut off. This failure was repeatable. Trouble-shooting revealed that air was entering the fuel system through the airframe fuel filter assembly drain valve.

The airframe fuel filter assembly, P/N 222-366-621-001, was replaced with P/N 222 366 621 003 and a ground run was carried out. The problem was rectified.

SDR # 20040825013

HUGHES 369D

Tail Rotor Gearbox Output Shaft Sheared



pilot reported that while descending rapidly, the collective bottomed out, and with right pedal input, the pedals and airframe would vibrate.

If a little collective input and left pedal were applied, the vibration would go away. The same defect was induced on the ground with right pedal input and the rotor with the RPM beeped to "MAX".

Investigation of the tail rotor gearbox revealed the output shaft, P/N 369D25430, had broken off where the inner race for the alignment roller bearing is pressed onto the inboard end of the output shaft.




Time Since New (TSN): 2 926.4 hours

Two similar occurrences were discovered in the SDR database, however, the two defects were discovered after the gearbox was inspected for generating metal.

en*gines*


TELEDYNE CONTINENTAL TIO-300-D (Cessna 172H) Carburetor Contaminated

SDR # 20040819001



Following engine startup after three months of inactivity; the pilot reported that the engine was running rough and that the carburetor was operating through only a limited range.

Maintenance personnel conducted an investigation and found a large mouse in the air box that was located near the carburetor venturi. The mouse was able to enter this area through the cabin heater ducting. The mouse nest contained seven infant mice!!



Ensure that the cabin heat control is closed to prevent similar occurrences.

feedback feedback feedback

heads UP

CESSNA 310


Wing Spar Cracked

The following defect was found during a 100-hour inspection of the aircraft (12 751hrs) where the wing centre section spar was found structurally failed.

The Aircraft Maintenance Engineer (AME) noticed wrinkles in the fuselage belly skin on the lower R/H side. Further inspection revealed that the forward centre section spar web had a small crack emanating from under a reinforcement bracket which is riveted to the front face of the web.

Upon removal of the reinforcement bracket, the R/H outboard seat rail, and the carpet covering the rear web skin, the AME discovered the top spar cap was cracked completely through. The front and rear spar webs were also cracked nearly their full height to the lower fitting.

A review of the aircraft technical records disclosed that the aircraft was substantially damaged in January 1979 (1 408 hrs), when the aircraft struck a snowdrift on the runway during landing. The upper spar cap may have received some damage during the accident, which was not discovered at the time of the repair. This damage would have been hidden by the seat rail, carpet, and reinforcement bracket.



Over the years, repetitive loading caused the spar cap to crack through and migrate down the face of the webs, behind the reinforcement bracket and the carpet. The crack finally became visible on the front spar web when the cracked propagated far enough as to not be obscured by this bracket.

The damage seen here could have started as a nick in the spar. The moral of this story is to be vigilant of unexpected defects when inspecting aircraft. Past damage history can be lost in the many volumes of technical logs and the AME may not be aware of this past history.

Transport Canada strongly recommends that owners and operators of aircraft that have previous accident history to inspect the repaired area at regular intervals. Early detection of crack growth can save lives and down time.

suspected Unapproved PARTS



There were no Service Difficulty Reports (SDRs) received between 1 July and 31 December 2004 that indicated any suspected unapproved parts.

In Canada, SUPs should be reported (CAR 591.01) indicating your suspicion of an unapproved part on a regular SDR form or on the Internet at:

www.tc.gc.ca/wsdrs

equip*ment ADs*

Transport Canada (TC) endeavours to send copies of new airworthiness directives (ADs), which are applicable in Canada to the registered owners of the affected products. Equipment/appliance ADs are often only distributed to our regional offices because the owners of aircraft affected by this type of AD are not generally known.

The following new ADs on equipment have been received by TC in the last three months. AMEs and operators of the affected products are encouraged to obtain further information or a copy of the ADs from their regional TC office, their local TCC, their PMI, or from the Civil Aviation AD website at:

http://www.tc.gc.ca/civilaviation/certification/continuing/ad.htm

Manufacturer	Ad Number	Origin	Description
AIRLINE CONTAINER	2004-22-01	US	Airline Container Manufacturing Company, STC ST01004NY Cargo Restraint Straps P/N 1519-MCID
CAMERON	G-2004-0026	UK	Shadow/Stealth Quad, Triple and Stratus Gimballed Burner Assy - Support - Inspection
HAMILTON SUNDSTRAND	2004-24-03	US	T-62T-46C12 AND T-62T-40C14 APUs - Fuel Filter Bypass Button - ASB-4504112-49-22 Rev 2
JANAERO	2004-25-16	US	14D11 OR 23D04 SERIS Fuel Regulator and S/O Valves Installed to B Series Combustion Heaters
KELLY/JANAERO	2004-21-05	US	B-Series Combustion Heaters - Models B2500, B3500, B4500 - Combustion Tube Distress
MANN	G-2004-0019	UK	Camera Installation-Floor Mounted Hold Down Hook - MAG(E) SB-A25-002, Issue 1
MICROTURBO	F-2004-177R1	FR	Limitation Of Cycle Number or Starting Saphir 20, Model 095
RECARO A/C SEATING	D-2004-151R1	GY	Seat Type 3410 - Seat Belt Retaining Fitting Bolt Connections. SB 3410-25MR477 Rev. 3

CONGRATULATIONS...

...to the following people who have won our door prize at the previous symposia!!!!

Chad Mitchell (Thunder Bay)

Claude Desjardins (Montreal)

John Latta (Vancouver)

Jim Graham (Winnipeg)

Gas Turbine ENGINE NOISE

"Sound" may be defined as that which can be heard. We know that sound can be heard because it consists of a series of pressure waves in the air. A sound can consist of a combination of many waves in a wide range of frequencies or consist of a pure tone, which is a single frequency wave that follows the sinewave pattern.

"Noise" may be defined as unwanted and usually irritating sound. The noise produced by a turbine engine consists of all frequencies audible to the human ear with intensities that can be extremely harmful to a person's sense of hearing.

"Decibel" (dB) is a measure of the intensity of sound. One decibel is one-tenth of a bel., the basic unit. For example, a barely audible sound has an intensity of 1 bel, whereas the sound intensity of a jet engine at takeoff power could be 155 dBs (15.5 bels).



A sound over 100 dB is considered very intense. The maximum level of sound that the human ear can evaluate is approximately 120 dB. Above, this level, the ear can feel increasing intensity but cannot hear the difference, thus ear damage can occur.

"One in 10 Canadians has a significant hearing problem with a third of the hearing losses associated with overexposure to noise."

The noise from a turbojet engine is basically caused by the incoming air being violently broken up and "sliced" into segments as it enters the inlet duct, passes through the inlet guide vanes, and encounters the compressor blades. The familiar "whine" noise is caused by the compressor blades "chopping" the incoming air. The most intense sound occurs at high power settings when the high velocity and hot exhaust gases leave the tailpipe and enter the relatively calm atmospheric air.

Over the years, engine manufacturers have been able to reduce exhaust noise by first developing the multiple-tube jet nozzle for commercial aircraft. This replaced the single exhaust pipe used on earlier commercial aircraft. The corrugated-perimeter type exhaust nozzle was also developed to further reduce noise levels. Later, the introduction of the turbofan engine allowed the primary and secondary airflow velocity enabled noise emissions to be further reduced. A reduction in velocity results in a decrease in noise intensity. Additionally, the high-bypass engines (4:1 to 8:1 bypass ratio) produce noise of lower intensity than the turbojet and the low-bypass because of improvements in engine noise absorbent linings in the fan ducts and exhaust nozzles. Also, new fan blades designs, improved exhaust systems, and more effective soundproofing materials have proven to be effective. There are, however, some add-on noise suppression units being currently developed to meet newer, more stringent regulatory noise requirements being introduced.

Ironically, sound can damage the inner ear. One in ten Canadians has a significant hearing problem with a third of the hearing losses associated with overexposure to noise. Ring noise (tinnitus) is a warning sign of dangerous overexposure to noise. Prolonged exposure to low power engine noise over 85 decibels for extended periods can also cause auditory damage. A turbine engine at take-off power can produce noise levels near 140 decibels, with a jet flyover producing approximately

100 decibels. Normal conversation is around 40 - 60 decibels.

It is highly recommended that maintenance personnel, ramp personnel and other persons that work on and around aircraft always wear approved hearing protection that completely covers the ears. Approved earplugs may be used as an alternative Ω



FAA Special Airworthiness Bulletins (SAIBs)

NUMBER	MANUFACTURER	MODEL/DESCRIPTION	DATE
SW-05-18	Agusta S.p.A	A109E	12/01/2004
CE-05-11	United Instrument, Inc	Altimeters	11/02/2004
SW-05-20	Eurocopter France	All models AS-350 and AS 355 helicopters	12/02/2004
CE-05-19	Marvel Schebler	Dual venturi type carburetors	12/02/2004
CE-05-12	Evektor Aerotechnik	L-13 SW and L-13SE motor gliders	11/04/2004
SW-05-10	Bell Helicopter Textron, Inc	205A, 205A-1, 205B, 212, and 412 series	11/05/2004
CE-05-13	Mooney Aircraft Corporation	M20M	11/09/2004
CE-05-15	Single or multi-engine	Pneumatic system components that power air-driven piston airplanes gyro instruments (Parker Hannifin-Airborne Division air pumps)	11/10/2004
CE-05-14	Parachutes Javelin	Student and Student Odyssey parachutes equipped with Adjustable Main Lift Webs harness and container systems	11/10/2004
CE-05-02	General Aviation	Airplanes that have rigid tubing routing flammable fluids such as fuel and oil to indicating gauges	10/18/2004
CE-05-04	Grob-Werke	All sailplanes	10/20/2004
CE-05-03	General Aviation	Possible problem with dry air pump installations using cork gaskets between the pump and engine drive pad	10/20/2004
NE-05-05	Schweizer Aircraft Corp	269C and 269C-1	10/21/2004
CE-05-07	PZL-Bielsko	SZD-50-3 sailplanes	10/22/2004
SW-05-06	Eurocopter France	AS355	10/22/2004
CE-05-09	Eaton Aerospace (Aeroquip)	Bulk hose material	10/25/2004
CE-05-08	Pilatus Aircraft Ltd	PC-12 and PC-12/45	10/25/2004
CE-05-02R1	General Aviation	Airplanes that have rigid tubing routing flammable fluids such as fuel and oil to indicating gauges	10/26/2004
CE-05-16	Centrair	ASW 20F, 101, and 201 series sailplanes	11/15/2004
CE-05-17	Cessna Aircraft Company, The	206	11/24/2004
SW-05-10R1	Bell Helicopter Textron, Inc	205A, 205A-1, 205B, 212, and 412 series	11/30/2004
CE-05-21	Alaska Tire & Rubber Co.	Alaska Bushwheel Tundra Tires	12/15/2004
CE-05-22	Raytheon Aircraft Company	390 Premier 1	12/17/2004
SW-05-24	Bell Helicopter Textron Canada	206A, 206B, 206L, 206L-1, 206L-3, and 206L-4	12/22/2004
CE-05-23	Dakota Cub	Fuel tanks	12/22/2004

FAA Unapproved PARTs Notification (UPNs)

The following UPNs were published by: FAA, AIR-140, P.O. Box 26460, Oklahoma City, OK 73125. UPNs are posted on the Internet at: http://www.faa.gov/avr/sups/upn.cfm

Date Posted	Number	Subject
12/27/2004	2004-00120	Prop Center – Improper Maintenance of Aircraft Propellers and Propeller Governors
12/17/2004	2002-00146	Aluminum Parts Heat-Treated by Temperform USA
09/28/2004	2003-00211	Engine Oil System and Fuel System Hoses
09/08/2004	2004-00051	Hose Clamps Installed in Bendix CADCs
09/08/2004	2003-00066	Illuminated Pushbutton Switches

FURTHER INFORMATION

The FAA would appreciate any information regarding the discovery of the above-referenced parts from any source and the action taken to remove them from inventory or service.

AME SYMPOSIA schedule

WESTERN - March 16 - 18

Coast Plaza Hotel & Conference Centre
1316 - 33rd Street NE, Calgary, AB T2A 6B6
Tel: 1-800-661-1464 or (403) 248-8888 Fax: (403) 248-0749
Internet: www.info@calgaryplaza.com

ATLANTIC - April 29 - 30

Delta Hotel St. John's

102 - 108 Kenmount Road, St. John's, NL A1B 3R2

Tel: (709) 722-9330 or 800-563-2489 Fax: (709)722-9231

Internet: www.csc@cityhotels.ca

service difficulty reports

Received by Transport Canada from 1 July to 31 December 2004

MAKE/MODEL	JASC	PART NAME	

PART NO. PART CONDITION SDR NO. RGN

a	ш	۲	c	r	а	ft	

	- C-3				
ER			0010/00	0004404004	546
					PAC
2/42	UPPER STRAP	1701971	CORRODED	20041209000	LIAN
2480	NILJUNKNOWN			20041129003	NCR
2150	BLEED VALVE	2856201		20040805011	QUE
	BATTERY		UNSERVICEABLE	20040803006	QUE
				20040727009	QUE
		NEACEDATIATEON	NO.	20040726010	QUE
			NO.		VAR
		PICO1244	LINSERVICEARLE	20041022003	QUE
			ONOLIVIOLIDEL	20040803004	QUE
	RELAY	350A67511001		20040805013	QUE
2913	PUMP SUPPORT	350A35101700		20040806010	PAC
2916	SAME	SAME	UNSERVICEABLE	20040803005	QUE
					QUE
					PNR
					QUE
					QUE
					QUE
6730					PNR
			MILLE		QUE
		11001211	UNSERVICEABLE	20040728007	QUE
					QUE
7321	FUEL CONTROL		UNSERVICEABLE	20040727011	QUE
	IGNITOR PLUG	9550175400	UNSERVICEABLE	2 SDRs	VAR
					QUE
					QUE
					QUE
	BI-DIRECT CROSS BEAM	350A381U1891	CRACKED	20041025004	PAC
6220		250 A 244 D 4 600			QUE
					PAC
		350A3321501	ONSERVICABLE		QUE
			STIFFA EAKINGAUS		VAR
			UNSERVICEABLE	20040727012	QUE
7532	BLEED VALVE		UNSERVICEABLE	20040727013	QUE
7930	TRANSMITTER	642790041			QUE
					QUE
			CRACKED		ONT
			I IN IOSEN HOSENDI S		ONT
	BALLERY		UNSERVICEABLE		QUE
			11/5	20041113000	PNR
					QUE
6320		350A32108203			PAC
	OIL COOLER BLOWER	355A340109		20040811008	PAC
6220	STARFLEX	350A31190703	UNSERVICEABLE	20040806005	QUE
2911	O RING			20040810003	ONT
		00000000000	OF LOWER	2024424262	210
					PAC
					PAC
					PAC
2230	BULI	MCPPIM	SHEARED	20041128010	FAC
2120	VADOR BARRIER		CRACKED/DIECES M	20040924001	QUE
		3905300101	OTTORILLE ILOCO IN		QUE
			PARTIAL DISCHARGE	20040916003	QUE
3230	TELESCOPIC STRUT	C2310961013		20041020003	QUE
0000	PRESSURE TRANSFER			20041123005	ONT
2910	DOOR BY-PASS VALVE			20040812009	QUE
3234	GEAR DOOR SEL V	114079016		20041202002	QUE
					QUE
			SHREDDED		QUE
	STEERING CIRL VALVE	2045122508			QUE
	3210 5742 2460 2150 2150 2150 2150 2150 2150 2150 215	2010 UPPER ARM ASSY	2742 UPPER STRAP 1701971	2480	2004103016 2004103016 20041209006 20041209006 20041209006 20041209006 20041209006 20041209006 20041209006 20041209006 20041209006 2004083006 2004083006 20040820016 20040820016 2004072001 20040805011 20040805011 20040805011 20040720501 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 200407205010 20040803004 20040803004 20040803004 20040803004 20040803004 20040803005 20040803

MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN
A320 211 A320 214 A320 231 A321 211	5300 3246 2121 7200	AIRFRAME TIE BOLT AVIONICS FAN ENGINE (TURBINE/	431304 ETV3454G	BROKEN FAILED	20041209001 20040812004 20041026010 20041209002	QUE QUE ONT QUE
A321 211 A321 211 A330 243 A330 243	7497 7930 1420 2330	ENGINTERFACE UNIT OIL TRANSMITER POWER UNIT CONNECTOR	3957985114 41:SG3811 8ES00650310	BURNT BURNT	20041214006 20041206002 20040908001 20040820002	QUE QUE QUE
A330 301 A330 343 A330 343 A330 343	2330 1420 3213 7310	MONITOR HARNESS BOLT LP FUEL LINES	7002061002 SEARCHING NAS6605D136 FK20824	BURNED CHAFED SHEARED	20041129006 20041108011 20041102001 20040924004	QUE QUE QUE
A340 313 BAE - UK	3442	WX RADAR ANTENNA	6225136201		2 SDRs	QUE
BAE 146 200 BAE 146 200 BAE 146 200 3112	5344 5741 5741 2120	UPPER HINGE ARM HYLOCK BOLT UNKSWING TO FUSELAGE CABIN HEAT DUCT	HC524H0344002 HL720PN1630 HC536H04230 1379219L401	CRACKED CORRODED UNSERVICEABLE OIL/SOLVENT SOAK	2004081100 20040915002 20041217004 20041109002 20041209009	ATL ATL ATL PNR ONT
3112 3112	2400 5610	AIRCRAFT WIRING RH WINDOW	379628C402	REPAIRED	20040930003	PNR
BAE - USA	2710	L/H AILERON TRIM	258CW1939A	CRACKED	20040902014	ONT
BAE 125 800A BAE 125 800A HS 125 800A BEECH	5753 5313	SHAFT ASSY TORQ (INNER) INTERCOSTAL (STRINGER)	25CF263321A 258FR7171	SURFACE CONTACT CRACKED	20041116005 20040902013	QUE
A100 A100	2731 2752	RELAY LH FLAP ACTUATOR	A41015455400 505212223	INTERMITENT	20040719003 20040915006	PNR
A100	3230	ACTUATOR	50820208	FAILED ENDPLAY	20041209014	ONT
A100 A100	3230 3244	ACTUATOR TIRE	99810057652 185F035	THREADS STRIPPED BLISTERED	20040705001 20041122004	ONT
A100	7120	CASTING	44911601	SEPARATED	20040803008	ONT
A100 B100	7322	NIL/UNKNOWN MAN FUEL/IGNITION	M2452426		20041122011 20040820008	PAC
B100	5610	WINDSHIELD	5042006936		20041124008	PAC
B200 B200	1100 2460	GPS DIODE	066040340204 70HF10 BURNT	INACCURATE OPEN	20040831021 20041025002	PNR
B200	2612	DETECTOR-FIRE & HEAT SE	NSOR 3001129	OPEN	20040805016	PNR
B200 B200	3050	GPS DATA ANTENNA AIRFRAME	CI2480100	VIBRATING	20040902008	PNR
B200C	3230	NOSE GEAR ACTUATOR		WORN	20040922005	ONT
B200C B300	3230 2435	SNAP RING END BEARING	NAS5150	OUT OF PLACE	20040922001	ONT
B300	5210	HINGE-DOOR HALF	50430043547	CRACKED	20040809006	PNR
B300 B300	5220 5344	CROSSTIE CHANNEL	97430000150 504300431329	CRACKED CRACKED	20040805017 20040916011	PNR
B300	5610	WINDSHEILD ASSY	1013840212	CHATTERED	20040806003	QUE
B99 B99	3246 3246	BEARING CONE INNER WHEEL HUB	950476 99800311	FAILED CRACKED	20040816009 20040916002	PNR
C90A	2432	CELL	32638002	REVERSED	20040917003	ONT
C90A C90A	2500 2730	CABIN LIGHT FIXTURE SPRING PIN	NAS427K6	UNSECURE	20040910001	THO
C90A	2823	FUEL SHUT-OFF VALVE	1013890253	FAILED	2SDRs	ONT
C90A C90A	3230 3230	LWR TORQUE KNEE PIN SWITCH	508100352 1013841377	CRACKED FAILED	20041015004 20040917004	PNR
100	0000	BLOWER ASSY	903840311	SIEZED	20041230003	PAC
100 1900C	2750 2820	ACTUATOR ENGINE FUEL FEED LINE	A31691	BENT WORN	20040911002 20040810004	PAC
1900C	2912	INLINE HYDRAULIC	KIT11480221S	SEPARATED	20040707002	PAC
1900C 1900D	3242 2312	STATIONARY DISC COMM TRANSCEIVER	114800817 6226152001	FRACTURED UNSERVICABLE	20041004003 20040824005	ONT
1900D	2612	FIRE LOOP WIRE	24412886	BROKEN	20040810002	ONT
1900D 1900D	3040	DEICE BOOT ACTUATOR	11418002823 11238002223	INTERNAL	20040705002 20041220002	ONT
1900D	3230	MOTOR ASSEMBLY	571302	UNSERVICABLE	20040707006	PNR
1900D 1900D	3230 5210	RELAY PRESSURE SEAL	MS24171D1 1294000371	SHORTED	20041220003 20040713008	ONT
1900D	5610	GROUND WIRE	MS250852BB5		20041109003	PAC
1900D 1900D	5610 5610	WINDSHIELD WINDSHIELD	PPG1013840257 10138402524	CRACKED CRACKED	20041221004 20041214003	ONT
1900D	7500	BLEED AIR TUBE	12991003363	CRACKED	20041208002	PNR
200	0000	SPAR WEB	5011002611	CRACKED	20041206008	PAC

MAKE/MODEL J	ASC	PART NAME	PART NO. P	ART CONDITION	SDR NO.	RGN	MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN
200 200 200 200 200 200 200	2752 3221 3230 3230 3230 3230 3230 3425 5210	FLAP MOTOR NEEDLE BEARING BLEED VALVE HYDRAULIC PUMP MASTER LINK RETAINING RING FLIGHT DIRECTOR SCREW	100384040 B66 ADI1SVA 1153800025 131378252CL MS168651031 7926355001 NAS51733	FAILED FAILED BLOCKED DISCONNECTED MISSING BENT	20040901009 20040902010 20040902012 20041112004 20041213002 20041022001 20041021005 20040819004	QUE PNR PNR QUE PNR QUE ATL PNR	 212 212 212 212 212 212 212 412	5302 5310 6320 6330 6710 7500 2100 2810	BULKHEAD PANEL ASSEMBLY SUPPORT CASE PYLON DAMPER SUPPO CONTROL TUBE P3 AIR LINE BEARING FUEL CELL	212030156047 2050328193 212040054005 DRT 212076101001 3017393 35BD219DUM 412361639101	CRACKED CRACKED BROKEN CRACKED BROKEN FAILED	20040812003 20040901008 20041123011 20040726009 20041007008 200411203008 20041208003 20041208003	ONT QUE PAC QUE PAC PAC ONT QUE
200 200 200 200 200	5270 5313 5341 5610	SWITCH FUSELAGE CROSS TIE COVER LH WINDSHIELD	V31 97430000115 5012010218 10138402521	CRACKED CHAFED SHATTERED	20041107001 20040927002 20041001013 3 SDRs	ATL PNR PAC PNR	BELLANCA 7GCBC 8GCBC# 8GCBC#	2160 2750 3220	MUFFLER FLAP CONTROL CAB LEAF SPRING	19023 315434	CRACKED FRAYED BROKEN	20041221003 2 SDRs 4 SDRs	PAC ONT ONT
95655 95855 959 959 959 959 959 959 959 959	2720) 23333251 24334 25230 2331 24334 23325 2332	RUDDER PEDAL ASSY RELAY GENERATOR SYSTEM SWITCH STEERING SUPPORT DOOR OIL COOLER SCOOP FIRE PROTECTION LANDING GEAR RETRAI OIL PUMP GEAR PITCH LINK, MIR TAIL ROTOR CASEY HEATER BATTERY FULL VALVE DRIVEN GEAR BEAR PAW UPPER SKIN RM STRAP BLADE FLAP RESTRAINT ARM MAST BEARING TRANS DRIVE SHAFT DRAG PIN ASSY TAIL ROTOR BLADE BEARING DISC ASSEMBLY INPUT SEAL LOWER BASE COMPRESSOR FULL PUMP TAIL ROTOR BLADE BYPASS SWITCH WASHER RESTRAINT DISC PACK MOUNT FITTINGS FUSEL AGE TAILEDOM LOW FUEL DETECTOR BLADE FUSEL SWITCH WASHER RESTRAINT DISC PACK MOUNT FITTINGS FUSEL AGE TAILEDOM LOW FUEL DETECTOR BLADE FUTTING FUTTINGS FUSEL AGE TAILEDOM LOW FUEL DETECTOR BLADE FUTTING RM FUTTINGS FUSEL AGE TAILEDOM LOW FUEL DETECTOR BLADE TITTING RM FUSEL FUTTING RM FUTTINGS FUSEL AGE TAILEDOM LOW FUEL DETECTOR BLADE TITTING RM FUSEL FUTTING FUTTING RM FUSEL FUTTING FUTTI	505243263 6046H39A V31 1158200557 50430043663 509102751229	STUCK CRACKED STUCK CRACKED SERVICEABLE CRACKED SPLINES WORN CRACKED INCORRECT RIGGING WRONG WIRE SIZE UNSERVICEABLE DRAWING AIR CRACKED CRACKED CRACKED CRACKED	20041026012 20041215003 20041115003 20041115003 20041115004 20040723007 20040829004 20040805010 200411070004 2004102001123005 200410107001 20041107001 200410107001 200410107001 200410100001 200410100001 200410100001 200410100001 2004010100001 2004010100001 2004010100001 2004010100001 2004010100001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001 200401000001	PRINT	BOEING 727 121 727 121 727 221 727 223 727 223 727 223 727 225 727 225 727 225 727 225 727 225 727 227 727 2201 737 701 737 701 737 701 737 701	5612 5753 27751 3270 27751 3270 2710 3280 3280 3280 3280 3280 3280 3290 3290 3290 3290 3290 3270 3270 3270 3270 3270 3270 3270 327	LWA FRONT SPAR PLATEAS WASHER & NUT CONTROL VALVE ASSY PLAPPOSITION INDICATOR TAIL SKID ACTUATOR MAIN CARGO DOOR CABIN COMPRESSOR SWITCH TENTORITY MAIN CARGO DOOR CABIN COMPRESSOR SWATCH TENTORITY NLG DOOR BRACKET STAB TRIM BRAKE FIREWALL BUJUH-EAD COL LANDINING EARA ACC MLG UPLOCK FITTING FIO PITTOT CARGO DOOR SEAL PRC FLAP POSTION TRANS ROD END BEARING NLG DRAG BRACE ASSY HYDRAULIC LINE ENGINE WHYD DOOR HINGE HYD PUSEL AGE MAIN, MA SLAT PROX SENSOR HYDRAULIC SYSTEM GUSSET LANDINING GEAR RETRAI NOSE GEAR LOCK ASSY RADAR ANTENNA ASSY FUSEL AGE MAIN, FUEL PLUMP RH MLG UPLOCK HYDR. DLTS UDDER ASSY SEB2-4 SPOILER C APP CARRIAGE TING BISCHARL SESSY NGINE SEDO DISPLAY UNIT	SSY 653120043 MSZ71113AN316 65404494 2081131 141169 65224787 4472R170 NNECTOR 656021132 65244809 AE4703100 106131713 B273201201 69222825 65178444440 66227741 CRACK 108122615 65448917 654581945 CTOR 651781914 20675680501 378200 AULIC LINE BACB30MT7723 69378778 65449617 894093	SEPARATED R MISSING FAILED FAILED CRACKED BROKEN CONTAMINATED NIERWA-SHORTOROUT CRACKED STICKING SEPARATED LACK OF LUBE DAMAGED CRACKED 2 SDRs ATL INTERMITTENT CRACKS FAILURE LEAKING SHEARED FRAYED CRACKED CRACKED CRACKED SMOKING	20041130002 20041118003 20041006002 20041001005 20041001005 20041025003 20040827001 2004127001 20041125001 20041027002 200410127002 200410127002 20040997007 20040993001 20040993001 20040993001 20040993001 2004093001	ONITION ON TO ONE ON THE ONE ONE ON THE ONE ON THE ONE ON THE ONE ON THE ONE ONE ON THE ONE ONE ON THE ONE ONE ON THE ONE ONE ONE ON THE ONE ON THE ONE ONE ON THE ONE ONE ONE ONE ONE ONE ONE ONE ONE ON
407 430 BELL TEXTRON - U 204B 204B 205A 1	2424 3210 3400 2460	TRANSMISSION TAIL ROTOR HUB COLLECTOR GEAR SHAFT VOLTAGE REGULATOR MAIN ROTOR BLADE SPHERICAL BEARING DC CONTROL UNIT	406012102109 222040111101 15891F 204011250113 212010783101 51509002R	HBFS218 U/S SCRAP	20040726002 20041005004 20041207004 20040901005 20040901003 20040821001 20040716004	ATL QUE NCR PAC PAC PNR QUE	757 258 757 28A 767 233 767 233 767 233 767 233 767 233 767 333 767 333	2210 M 2742 S 2752 RI 7200 E 7314 EI 7312 SI 7314 HI	VBC CHANGED NG DRIVEN PUMP ERVO FUEL HEATER P FUEL PUMP	BV031120333 113T12518 7765557 350880 702101601425 1383M68P12	CORRODED SHAFT SHEARED CONTAMINATED	20041021008 20041022002 2 SDRs 20041229001 20041229009 20041129009 20041129007 20041123006	PAC PAC QUE QUE QUE QUE QUE QUE
212 212 212 212 212	2810 2810 2841 2900 2911	CAP FUEL CELL LH FUEL QUANTITY HYDRAULIC HOSE ASSY ACCUMULATOR - HYDR.	205031709052S 391046199 7012J220W234	CORRODED UNSERVICEABLE BURST UNSERVICEABLE	20040812006 20041123012 20041109008 20040910002 20040728005	ONT PAC QUE QUE QUE	767 375 767 375 767 375 767 375 767 375 767 375	1497 L/ 3213 M 5610 C/ 7332 FL	AV AC'L WIRING L GEAR AXLE APT'S WINDSHIELD UEL PRESSURE TRANSM HAND BLEED SYSTEM	H75C20 161T11387	BURNT AXLE BROKEN LEAKING LEAKING	20041123003 20041126010 20040813003 0040812010 20041230002	QUE QUE QUE QUE QUE

(E/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN	MAKE/MODE	LJASC P	ART NAME	PART NO.	PART CONDITION	SDR NO.	RG
IBARDIER 100 1A10	2400	AIRCRAFT			20041103009	NCR	CASA C 212 CC50	2910	HYDRAULIC HOSE	NAVARIOUS	3 YEARS OLD	20041230001	1 0
100 1A10	2913	DC HYDRAULIC PUMP	9558053	NEW	20041012003		• CESSNA	0000		107.10	OFDAD ATED	000 40700000	
700 1A10	0000	MAIN PLUNGER	GC4153259	REVERSED	20040916001	QUE	A185F	3233 5342	HYDRAULIC LINE	42749 07321014	SEPARATED CRACKED	20040728003 20040825002	
700 1A10 700 1A10	2497 2750	SPDA CONNECTOR SLAT FLAP CONTROL	770699A 763077J	BURNT MARKS	20041004006 20040930007	NCR NCR	• A185F • A185F	5753	FLAP PULLEY BRACKET		UNSERVICABLE	20040823002	3 P
700 1A10	3416	INTEGRADED STDBY	C1621AA02	BROKEN	20041124001	QUE	R182	2750	FLAPS UP LIMIT SWITCH		ONOLIVIONDEL	20041014004	
00 2024	2740	MCU	70744		20040918002		R182	5344	DOOR HINGE	071103720	CRACKED	20040804010	9
TEN NORMA							• TR182	3242	LANDING GEAR PIVOT	224110213	ORGINAL	20040927008	
2A	3242	INBOARD WHEEL HALF	16104700	CRACKED	20041104005	PAC	TU206G	8011 3260	GEAR GEAR WARNING HORN	539785	BROCKEN FAILED	20040805002 20040723003	
ADAIR 15 1A10	2913	O RING	MS2877810	BLOWN	20040728010	PAC	T310R T337G	2215	CABLE	99100802 15600088	FRAYED	20040723003	
15 1A10	3414	AIRSPEED INDICATOR	14261ZA1	DECTVIA	20041201001	QUE	T337G	5730	UPPER WING SKIN	14220006	CRACKED	20040930002	
15 1A10	5270	MICROSWITCH BRACKE		BROKEN	20040720010		U206B	3211	FITTING	1216012	CRACKED	20040823005	
15 1A10	5311	FRAME ANGLE	21531036212	U/S CRACKED	20041018003	ATL	• U206C	3221	BOLT	NAS464P5A42		2 SDRs	
15 1A10	8550	NOSE CASE PLUG INSERT	177770		20040825006	PNR	U206E	2810	RESERVOIR	121640719	CRACKED/STRIPPED	2 SDRs	
156B11(CL415)	2510	SEATBELT WEBBING	5023384272251	CHAFED	20041018010 20041203001	QUE	U206F U206F	2510 7322	INERTIAL SEAT BELT WEB THROTTLE CABLE	S21994 MCC29950501	BROKEN	20041102004 20041006008	
156B11(CL415) 00 1A11(600)	2897 7830	ELECTRIC WIRE BEARING	SM141038	SCRAPPED	20041029002	NCR	• U206G	2750	BOLT	AN34A	STRIPPED	20040924006	
00 2A12(601)	2420	ACCENERATION SYSTEM	CHITTIOO	OCI G I I LD	20040729002	ONT	. U206G	3211	FITTING MLG	12116013	CRACKED	20040924008	3 1
00 2A12(601)	2700	PROXIMITY SWITCH	PS1CC		20041126007	QUE	 150L 	2750	FLAPTRACKS	0523113	WORN	20041110006	
00 2A12(601)	2750	BRAKE DETECTOR UNIT	60093000103		20041126002	QUE	150L	2750	WING FLAP TRACKS	05232113	WORN	20041110005	
00 2A12(601)	2750	SYSTEME DE FLAPS	0000000405		20041001010	QUE	150L	5210	L/H FWD DOORPOST RIB ASSY LEADING	04118685	CRACKED BROKEN	20041110007 20040907001	
00 2A12(601) 00 2A12(601)	3260 5711	ACTUATEUR TRAIN WING ASSEMBLY	6008500185 6001000011001	CRACKED	20041108012	QUE	150L 150L	5551 5610	WINDSHIELD	0413419201	CRACKED BROKEN	20040907001	
0.2B16(601 3A)		PLUNGER(INDICATOR)	91111	JAMMED	20041100002	QUE	150L	5712	INBOARD WING RIB	042650720	CRACKED	20041110004	
0.2B16(601 3A)	2360	DIPERDITEUR ILEC	217SC1	BURNT	20041122001	QUE	• 150L	7931	LINE ASSEMBLY	040031178	WORN	20041130004	
0.2B16(601 3A)		WIRE HARNESS			20041115005	PNR	150M	2710	CABLES	040010741	CORRODED	20041109004	
0.2B16(601 3A)	3260	ACTUATOR	0005045000	MAN EN INJECTION IN IC	20041223002	QUE	152	2720	RIGHT RUDDER CAB FLAPS SYS INDICATOR	0400107150 04602109	FRAYED	20041123007	
0.2B16(601.3A) 0.2B16(601.3A)	7200	STALL PROTECTION MOTEUR GAUCHE	6005915229	MALFUNCTIONING	20040722003	QUE	152 152	2751 3220	NOSE GEAR FORK	04602109	CRACKED	20041101008	
2816(601 3R)		PRESSURE REGULATOR	4020T35G04	DEFECTIVE	20040804009	QUE	152	7602	MIXTURE CONTROL	AN742D3	LOOSE	20041215002	
00 2B16(604)		INSPECTION CRANK	6078T58P01	00,001110	20041001009	QUE	170B	5520	LH ELEVATOR BRACKET		CRACKED	20040825004	
0 2B16(604)	0000	NILJUNKNOWN			20040726006	ONT	170B	7120	LH UPPER ENGINE RAIL		CRACKED	2 SDRs	
00 2B16(604)		RADIO TUNING UNIT	6229852124	FAILED	20040728002	PAC	172M	2311	RADIO MASTER SWITCH		FAILED	20041014002	
00 2B16(604)		TIP MAINIPATTED CHAPCED	600151103	FRAYED FAILED	20040817008 20040728001	PAC	172M 172M	2430 2701	ALTERNATOR BEARING SPACER	DOFF10300J	LOOSE	20041015001 20040809004	
00 2B16(604) 00 2B16(604)	2432 2700	MAIN BATTERY CHARGER TRANSMITTER BRACKET	601R593251	INSUFFIENT CLAMP	20040726001	ONT	172M	3246	HUB ASSY	D30256	CRACKED	20041014008	
00 2B16(604)		AOA TRANSDUCER	25147A7L1T2	BEYOND SERVICE	20041101005	ONT	172M	5210	PUSH ROD ASSY	05170281	BROKEN	20041103005	,
00 2B16(604)		AIR SUPPLY			20041224007	PAC	172M	5311	BULKHEAD	05120111	CRACKS	20041105004	
00 2B16(604)		UPPER CORE COWL	A33721		20041001014	QUE	172M	5753	RAFLAP	74070	CRACKED	20040708009	
0 2B19(RJ)	2197	CIRCUIT BREAKER	47050704	FAILED	20040829002	ATL	172M	8530 2497	INTAKE FLANGE GASKET	/19/3	SPLIT FAILED	20041122003	
0 2B19(RJ) 0 2B19(RJ)	2612	FIREX CONTROL UNIT	47259701 270007	FAILED	20040811002	NCR NCR	172N 172N	2701	ALTERNATOR ROD END	C109	WORN	20040809005	
0 2B19(RJ)	2910	HYD PUMP	848847	CASE CRACKED	20041129014	QUE	172N	2740	CABLE ASSEMBLY	051010545	FRAYED	20041216006	
0 2B19(RJ)	3234	GEAR SELECTOR VALVE	555406		20041217002	ATL	172N	5312	BULKHEAD	05123635	CRACKED	20041216007	
00 2B19(RJ)	3234	VALVE	750006000		20040816003	QUE	172P	2752	ACTUATOR COUPLING	C3010020211	BROKEN	20041129011	
0 2B19(RJ)	3260	PROX SENSOR CONT			2 SDRs 20040818002	VAR NCR	172P 172P	3243 5347	PISTON SEAT STOP	98820125 05112421	BROKEN SEPARATED	20041007005 20040831017	
0 2B19(RJ) 0 2B19(RJ)	5300	STALL COMPUTER FUS FRAME, LH/RH		CRACK	20040803010	ATL	172R	2410	ALTERNATOR CTRL UNIT		FAILED	20041130011	
0 2B19(RJ)	5300	NIL/UNKNOWN		Orthor	20040802001	ATL	172R	3300	LANDING LIGHT SWITCH		WORN	20040916010	
0 2B19(RJ)	5312	FUSELAGE MAIN, **	CRACKS		20041224003	QUE	172S	2421	ALTERNATOR CONTACTOR	X660007	INTERNAL DAMAGE	20040907002	
0 2B19(RJ)	5610	L/H WINDSHIELD	NP13932111	CRACKED	3 SDRs	NCR	• 172S	8550	ENGINE MOUNT	27400074	OD LOVED	20040831019	
0 2B19(RJ)	5610	RH COCKPIT SIDE	NP1393226	CRACKED	3 SDRs	VAR	180C	5313 5530	REINFORCEMENT	07122071 07310041	CRACKED	20041110015 20041108005	
0 2B19(RJ) 0 2B19(RJ)	5610 5610	RHCOCKPITWINDSHELD SIDE WINDOW	NP13932110 NP1393221		20041223006 20041031003	QUE	180C 180C	7120	VERTICAL STAB ENGINE MOUNT	07510041	CORRODED CRACKED	20040723006	
0 2B19(RJ)	5610	WNDOW	NP1393225		20041129001	NCR	180H	2731	ELEVATOR	0/5/00/25	FAILED	20040730007	
0 2B19(RJ)	5610	WINDSHIELD ASSY	601R3303310	CRACKED	20041018001	ATL	180H	5510	RENFORCEMENTERACKET	07321014	CRACKED	20040825003	3
0 2B19(RJ)	7110	CAMLOCK	40S16111AA	WEAK	20040814001	ATL	180J	3246	DECK STRAP	16449	CORRODED	20040915008	į.
0 2B19(RJ)	7110	CAMLOCK GROMMET	40G15160S	WORN OUT	20040814002	ATL	180J	7120	LONGITUDINAL TUBE	07440044	CRACKED	20040915010	
0 2B19(RJ)	7110	NOSE COWL UPPER	22850080158	DAMAGED	20040811003	NCR	182E	3213 3230	LIH MAIN LANDING	07416011 07416011	BROKEN GOOD	20040917006 20041108003	
0 2B19(RJ) 0 2B19(RJ)	7200 7261	ENGINE ENGINE			20040908006 20041115001	NCR	182G 182Q	2710	SPRING ASSEMBLY BLOCK	07606331	WORN	20040913003	
0 2B19(RJ)	7314	ENGINE FUEL PUMP	6078TP04		20041031001	NCR	182S	3340	LANDING LIGHT SWITCH		OVERHEATED	20041012006	
0 2B19(RJ)	7714	STATOR - ALTERNATE		OPEN CIRCUIT	20041103002	ATL	207	5551	DOUBLER AFT SIDE	12120031	CRACKED	20040904001	
0 2B19(RJ)	7830	LOCK OUT SWITCH	1EN2893	INTERNAL DEFECT	20041226002	NCR	207A	8530	PUSH ROD	538304	BROKEN IN TWO	20041210003	
00 2C10(RJ)	2720	RUDDER TRAVEL LIMITER	SDBA670934000	1 NEW	20040915001	NCR	208	2750	FLAP MOTOR	C145350	LOOSE	20041108006	
0 2C10(RJ)	2820	FUEL EJECTOR	T99A38603		20041224002 20041010003	QUE	208B	3252 7120	SHIMMY DAMPENER ACCONDENSOR CLAMP	26430096 26014171	BROKEN ORIGINAL	20040810005	
00 2C10(RJ) 00 2C10(RJ)	3230	DOWNLOOK ASSIST VALVE ADAPTER	533415 MS276125	FAILED	20041010003	NCR	208B 208B	7321	FUEL CONTROL UNIT	20014171	CHIGHAL	20041019003	
0 2C10(RJ)	5280	RH MLG DOOR	CC67010520	1 MLLD	2 SDRs	QUE	310R	5711	FITTING UPPER	08113507	CRACKED	20041119001	
00 2C10(RJ)	5610	LH SIDE WINDOW			20040815001	NCR	• 337A	3246	BOLT	AN36A	MISSING	20041020011	
00 2C10(RJ)	5610	WINDSHIELD	NP13932112	CRACKED	20040704001	NCR	337G	3260	SWITCH	YZ2RQ1T	CRACKED	20040720007	1
00 2C10(RJ)	7230	ENGINE	CF348C		2 SDRs	NCR	• 401B	3230	IDLER BELLCRANK	05411066	UNSERVICEABLE	20041025001	

MAKE/MODEL	JASC	PART NAME F	PART NO. P	PART CONDITION S	DR NO.	RGN	MAKE/MODEL	JASC	PART NAME	PART NO. P	ART CONDITION	SDR NO.	RGN
414	7931	TUBE - OIL	5100106236	CORRODED	20041006005		DHC 7 102	3260	MAIN LANDING GEAR	1510015	WONT RETRACT	20041130003	ONT
441 550	5751 2120	BELLCRANK SUPPORT SLEEVE	5/150021 CM357024	CRACKED DISCONNECTED	20041110019 20041130001		DHC 8 100 DHC 8 100	2120 2700	PRESSURE REGULATOR ACTUATOR	A44700009	CRACKED HOUSING	20040708003	NCR NCR
550	2300	WIRE HARNESS	RMU850	CHAFFED	20040726004	ONT	DHC 8 100	2720	SWITCH	682015	HUNG UP	20040901004	NCR
550	2397	COMMUNICATION SYS			20040715003	ONT	DHC 8 100	5311	FRAME			20040708002	NCR
550	3230	BOLT	NAS464P538	SEIZED	20041103001		DHC 8 100	6122	PCU AUTO DU OT CEDUO	78249050		20040707004	NCR
550 550	3242	STATOR DISK	1338931 1338932	CRACKED BROKEN	20040730004		DHC 8 102 DHC 8 102	2215	AUTO PILOT SERVO ELECTRICAL POWER	7002260723		20040714002 20040911001	ATL
550	3243	PUMP ASSEMBLY	99121661	LEAKING	20041020006		DHC 8 102	2435	BEARING	03600923	FAILED	20041102007	PAC
550	3400	ADI HARNESS			20040816006		DHC 8 102	2510	TUBE - WELDED	1B11071	CRACKED	20041026006	ATL
550	7120	CAP	55120416	WORN	20041015003		DHC 8 102	2611 2710	SMOKE DETECTOR	3023143 NAS427K23	NO FAULT	20041029010 20041007007	PAC
550 550	7321 7900	FUEL CONTROL UNIT	32447504	FAILED DEBONDED	20041115003		DHC 8 102 DHC 8 102	2752	GUARD FLAP BALLSCREWACTU		MISSING	20040715002	PAC
560	2130	VALVE	471319X	FAILED	20040830007	PAC	DHC 8 102	2900	RCCB	SM601BA20A1	INOPERATIVE	20040819011	ATL
560	2350	ELECTROLUMINESCE F	PANEL	NOT ILLUMINATED	20040830004		DHC 8 102	3230	M.GREIRACTIONACTUATOR		FAILED	20041101001	ATL
560 560	2782 3160	PWD PLAPFOLLOWUPCA DISPLAY SCREEN	BLE 656014131	FAILED / BROKEN FAILED	20041126001		DHC 8 102 DHC 8 102	3230 3234	PROXIMITY SENSING UNIT LDG SELECTOR VALVE	841005 7SC0143	FAILED	20040810001 20040716002	ATL
560	3246	THERMAL RELIEF PLUG AS	SY 49330	LEAKING	2 SDRs	PAC	DHC 8 102	5300	NILIUNKNOWN	7300143	PALED	20040801001	ATL
560	3300	RELAY	M835369024	CONT.WELD CLOSED	20040830005	PAC	DHC 8 102	5730	WING PLATES/SKI	DHC8102	CORROSION	20041025003	ONT
560	3497	GNSXL FMS	1835501010001				DHC 8 102	6122	VALVE ASSY FEATURE	7897501		20040729001	ATL
560 560XL	7322 2710	CUTSIDESLEEVECABLEASS	666000163	WORN BROKEN STRANDS	20041007006		DHC 8 102 DHC 8 102	7200 7700	TURBO MACHINERY WING ROOT CONNECTOR	MS347L2255PN	FAILED	20040829001	ATL.
750	2722	POWER CONTROL UNIT	00000100	DIVORED STITUTED	20040805018		DHC 8 102	7931	GAS GENERATOR CAP	01R311159601	CRACKED	20041018011	ATL
CHAMPION							DHC 8 102	7933	OIL TEMP/PX INDICATOR		READING LOW	20041103008	PAC
7ECA	5710	WING STRUTATTACH FITTING	G 31692	CHAFED	20040817006	PAC	DHC 8 200	2134 7931	PRESSURE SWITCH FLEXIBLE HOSE ASSY	7G959 DSC3912	OUT OF TOLERANCE	20041012007 20041007003	NCR NCR
CONAIR FIRECAT	3233	O-RING	MS28775212	FAILED	20040702004	PAC	DHC 8 200 DHC 8 300	2422	PRIMARY INVERTER	DH103024600C		2 SDRs	NCR
CONVAIR - CAN		O MINO		1 1 Whataday			DHC 8 300	2910	BRAKE LINE			20041221008	NCR
340	3246	INNER RACE	34479	CORRODED	20040728006		DHC 8 300	2910	HYDRAULIC TUBE	82910009123		20040823001	NCR
340 340	5230 8011	C1 CARGO DOOR INTERNAL SWITCH			20040818004		DHC 8 300 DHC 8 300	2932 3234	PRESSURE SWITCH MLG SEL	7G772 574205A		20041004001 2 SDRs	NCR NCR
440	2100	WATER SEPARATOR	80170		20041104001		DHC 8 300	3244	TIRE	DSC428		20041123002	NCR
440	2610	GASKET	24346300C	MISSING	20040804001	PAC	DHC 8 300	3260	PSEU	858601		20041122012	NCR
440	2800	AIRCRAFT	0000004	DUDTH IDED	20041004004		DHC 8 300	3300	CONNECTOR		BURNT	20041207001	NCR
440 440	2910 5230	HYD PRESSURE LINE AIRFRAME	9036261	RUPTURED	20040819013		DHC 8 300 DHC 8 300	3310	RHEOSTAT (READING) COMPUTER	101741111	BURNT - INTERNAL	20040720009	NCR NCR
440	7810	TURNBUCKLE	NAS27844	SHEARED	20040719006	PAC	DHC 8 301	2435	BEARING	03600923	FAILED	2 SDRs	PAC
440	7921	CIRCUIT BREAKER	D6752110	STICKING	20040823002		DHC 8 301	2510	TUBE - WELD BASE	1B11071	CRACKED	2 SDRs	ATL.
DASSAULT	7921	OIL COOLER DOOR	315341	FAILED	20040806001	PAC	DHC 8 301 DHC 8 301	2913 3233	COUPLER & SHAFT BRAIDING	570717570729	BADLY WORN BRAIDING FAILED	20040915004 20040823006	ATL
FALCON 10	2612	FIRE LOOP SENSOR	3001169004001	2 OPEN CIRCUIT	20041222007	ONT	DHC 8 301	3300	BATTERY PACK		DIVINO I MILLO	20041208001	ATL
FALCON 10	2842	FUEL QUANTITY AMPLIFIER		INOPERABLE	20041222008		DHC 8 301	5210	SEAL - FWD EMERG	852202081007	WORN	20041122016	PAC
FALCON 10 FALCON 20	7331 2700	FUEL FLOW GAUGE MOTOR	7231602 27529030	FAILED OVERLOADED	20041222009	ONT	DHC 8 311 DHC 8 311	2421	AC GEN ADAPTER INVERTER	31708500 DH103024600CS11E	STUDS PULLED 3 FAILED	20041126008	PAC
FALCON 900	3416	AIR DATA COMPUTER	7000700647	CAEKTOVOED	20040907005		DHC 8 311	2424	GENERATOR CONTROL		NII	20041122015	PAC
FALCON 900	7230	TURBOFAN	TVT10728H3		20041028001		DHC 8 311	2435	BEARING	03600923	IN PIECES	20041006003	ATL
	CAN	MOLTAGE CONTROLLE		DI IONE	000 40000040	OUE	DHC 8 311	3411	PITOT/STATIC SYS	2020000	EAH ED	20041102006	QUE
DHC 2 MKI DHC 2 MKI	2432	VOLTAGE CONTROLLER GENERATOR	1381	BURNT FAILED	20040928013 20040830011	QUE PNR	DHC 8 311 DHC 8 311	7200 7311	TURBO MACHINE FUEL/OIL COOLER	3038300 10750F	FAILED INTERNAL LEAK	20041029009 2 SDRs	PAC
DHC 2 MKI	2730	ELEVATOR CONTROL C		FRAYED	20040928012	QUE	DHC 8 311	7933	OIL PX/TEMP IND.	523281	READS HIGH	20040923003	ATL
DHC 2 MKI	3243	MASTER CYLINDER	C2CF1343A	DISOUDER	20040716003		DHC 8 314	5610	WINDSHIELD	8SC0043014	CRACKED	20041209004	ONT
DHC 2 MKI DHC 2 MKI	5510 5520	STAB ATTACH BRACKET	C2TP159 C2TE29ND	CRACKED CRACKED	20040927009 20040831003		DHC 8 400 DHC 8 400	2612 2742	FIRE LOOP PITCH TRIM ACTUATOR	10109601 3994001009		20041206001 2 SDRs	NCR NCR
DHC 2 MKI	5521	ELEVATOR	C2TE139ND	ONTONED	20040915009		DHC 8 400	2752	NILJUNKNOWN	302400 (000		20040831010	NCR
DHC 2 MKI	5552	BOLT	AVV46	WORN	20040713004		DHC 8 400	2913	HYDRAULIC PUMP	6617302		4 SDRs	NCR
DHC 2 MKI DHC 2 MKI	7322 7414	BELLOWS MAGNETO	C2E2215 SB9RU3	FAILED FAILED	20040702002 20040810006		DHC 8 400 DHC 8 400	3233	MLG RETRACTOR HOSE LANDING GEAR SELECTOR			20041019002 20040824002	ONT
DHC 2 MKI	7414	MAGNETO DRIVE SEAL	383021	WORN	20040928003		DHC 8 400	3246	MLG WHEEL ASSY		CRACK	20040805003	NCR
DHC 2 MKI	7800	EXHAUST STACK	576	BULGED	20040915007		DHC 8 400	3260	NLG PROXIMITY SENSOR	401020101		7 SDRs	NCR
DHC 3	0000	TIE ROD	AN679AC6000	BROKEN	20040923004		DHC 8 400	3260 3418	WOW NO. 2 HARNESS ANGLE OF ATTACK	04047740		20040824001	NCR
DHC 3 DHC 3	2520 2731	AMSAFE 6000 FLUTTER MODIFICATION	6000 VALTOC113620	NEW	20040813005		DHC 8 400 DHC 8 400	5210	GOOSENECK ASSY	C16177AC 85217051101		20041020001	NCR NCR
DHC 3	2731	ROD END	C3CF4205	EXCESSIBLY WORN	20040928007	ONT	DHC 8 400	6120	PROPELEC CONTROLLER			3 SDRs	NCR
DHC 3	5610	LH & RH WINDSHIELD	0.453.44.0500	CORRODED HOLES	20041221007	PAC	DHC 8 400	7410	IGNITION EXCITER			20040922004	ONT
DHC 4 DHC 6	5230	HINGE ARM FITTING SLIDE ACTUATOR	C4BM13583 PDMC6E101729	CRACKED NEW	20041222002		DHC 8 400 DHC 8 402	7712 2913	TORQUE PROBE BYGINE HYDRAULIC PUMP	6617302	NEW	20041020008 20041124006	NCR
DHC 6 100	2430	SWITCH	MS3505923	FAILED	20041104009		DIAMOND - AS	2010	DANKLINGARCION	001/302	CHEST	20041124000	COL
DHC 6 300	0000	BOLT, ENGINE	CSP28229	USED	2 SDRs		DA 40	5520	BUSHING	PAF06080P11	MISSING	20041125005	ONT
DHC 6 300 DHC 6 300	1000 2810	BARREL NUT AFT TANK FUEL CAP	B42624	THREADS DAMAGED	20041001008 20040712001	ONT NCR	DIAMOND - CAN DA 20 C1	2750	SPLINED SEAL	UNIDENTIFIED	LOOSE	4 SDRs	ATL
DHC 6 300	3220	BOLT	711731	SHEARED	20040722001	QUE	DOUGLAS				20002		ALL.
DHC 6 300	3246	FLOAT PLATE	C6FSM225627	NEW	20041206005		A26	8500	SEAL	28151	OD LOVER	20040708011	PNR
DHC 6 300 DHC 6 300	3250 7120	CABLE BOLT ENGINE	C6CF12425 CSP28229	SAWED THROUGH NEW	20041216001 20041216005		A26C B26C	8530 8500	CYLINDER ENGINE		CRACKED	20040820005	PNR
DHC 7 102	2913	HYDRAULIC PUMP	6305402	FAILED	20041013008		DC9 83	1420	NILIUNKNOWN			20040623006	QUE
						,							

MAKE/MODEL	JASC	PART NAME	PART NO. P	ART CONDITION	SDR NO.	RGN	MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RG
DC9 83	2150	AIR CYCLE MACHINE			20040823003		LEARJET						
DC9 83 DC9 83	2400	POWER RELAY ALTERNATOR-GENERATOR			20040728008 2 SDRs	QUE	35 35	2100 2435	DRAIN TUBE GENERATOR	24192273 66082019	BURST	20040721001 20041202003	
DC9 83	2421	AC GENERATOR-ALT			20040917001	QUE	35	2910	HOSE HYDRAULIC	2307006101	LOOSE	20041101002	
DC9 83	2612	FIRE DETECTION			20041104002	QUE	35	3244	TIRE	173K233	CUT	20040713003	3 QU
DC9 83	2750	TE FLAP CONTROL			20040805012		35	3260	LANDING GEAR POST	2242527	CD LOVED	20041222001	
DC9 83 DC9 83	2913 3100	HYD PUMP RECEPTACLE PIN		WRONG TYPE INST	20040727007 20041102011	QUE	35 35A	5343	WEB TUBE ASSEMBLY, DRAIN	2310537	CRACKED RUPTURED	20040929002 20040918001	
DC9 83	3140	GENERATOR SYMBOL		WINCHO I I'VE INOT	20041020007	QUE	35A	3221	FWD PRESS BULKHEA		KOFTOKED	20040716001	
DC9 83	3244	TIRE			20040928006	QUE	9 35A	3244	TIRE	5004913		20041126003	QU
DC9 83	5230	CARGO/BAGGAGE DOOR	504005000	CORRODER	20041005005		35A	3244	TIRE (GOODYEAR)	178K235	DAMAGED	20040818001	
DC9 83 DC9 83	5260 5270	TUBE DOOR WARNING SYS	591885323	CORRODED	20041105001 20041026005	QUE	35A 45	3500 2432	OXYGEN LINE EMERGENCY BATTERY	2519C5912 7624308001001	CRACKED	20040820001 20040715004	QU PN
DC9 83	5300	FUSELAGE STRUCTURE			20040819012		45	2750	FLAP POWER UNIT	C1444831	NOISY/SLOW	20040705008	
DC9 83	5610		5912290506		20040831006		45	3231	GEAR DOOR BELLCRANK	4532103045002	CRACKED	20040705003	
DC9 83 DC9 83	7200 7603	ENGINE POWER LEVER			4 SDRs 20040831018	QUE	45	3233	GEAR DOOR ACTUATOR WIRES	6632303003001 F23B22	CAPPED & STOWED	20040705007	
C9 83	7711	TRANSMETTER PRES			20040631016	QUE	LOCKHEED	3445	ANIMES	F23D22	CAPPED & STOWED	20041110014	CAC
DC9 83	7920	ENGINE OIL FILTER			20040820007	QUE	188A	5310	R/H FRAME	8010302	CRACKED	20040909002	
DC9 83 DC9 83	7920 8012	OIL LINE	7938314506	CRACKED	20041214004 20040712007	QUE	188C 382G	7320 6120	FUEL CONTROLLING PROP VALVE			20041105005 20040803002	
MBRAER	0012	START VALVE			200407 12007	COE	MCDONNELL DO					20040003002	. On
EMB 110P1	5753	BOLT	AN33A	LOOSE	20040827006	PNR	600N	6210	M/R BLADE ASSY	369021102523	CRACKED	20041104010	PN
UROCOPTER DE	EUT	CEDVO VALVE	40F 40000	CDACKED	20040712005	CALIT	MITSUBISHI - USA MU 2B60		ELEVATOR OLIADRANE		DAMAGED	20040720004	01
BK117 BK117 B 1D	6730 2913	SERVO VALVE HYDRAULIC PUMP	10546682 40165	CRACKED NOISYMHINING	20040712005 20040928008		MOONEY	6110	ELEVATOR QUADRANT		DAMAGED	20040720001	ON
30105 C CDN BS	6320	BEARING	4638302024	SCRAP	20040712003	ONT	M20E	5753	HINGE BLOCK	240014901	SEVERE CORROSION	20040712009	ON
80105 SCDN BS 4		BANJO BOLT	RA13212	LOOSE	20041019001	ONT	MORAVAN						
BO105 SCDN BS 4		BOLT BUSHING	LN9038 10560386	MISSING/LOOSE DEBONDED	20041015002 20040708001	ONT	Z242L Z242L	2731 3250	SHAFT SPRING	Z4244100011 Z4242170001	SHEARED BROKEN	20041215006 20040831009	
30105 SCDN BS4		IGNITION EXCITER	103871501	DEBONDED PLUG	20040726005		NOORDUYN	3230	SPRING	24242170001	BRUKEN	20040031008	ON
UROCOPTER FF	RANCE						NORSEMAN MK V	2421	ALTERNATOR	7755T		20040831004	ON
EC 120 B	3040	L/H WINDSHIELD	C561S1101202	DEBONDED	20040914005		PIAGGIO	2200	CVD WIDING		MEDING MEDING	20040727004	ON
EC 120 B EC 120 B	6520 7314	MAGNETIC PLUG CHIP FUEL PUMP	7052A3632279 P94C16612	CRACKED TRIPPED C/BREAKR	20041014001 20040914003	PAC	P180 AVANTI P180 AVANTI	2300 2360	CVR WIRING STATIC WICK BASE		WRONG WIRING	20040727001 20041019006	
AIRCHILD							P180 AVANTI	3040	DE-ICE VALVE	BYLB51824		20040712004	ON
SA227CC	7714	LH RPM INDICATOR	2719157005	NOT OPERATIONAL	20040920004	ONT	P180 AVANTI	3246	WHEEL ASSEMBLY	314611	CRACKED	20041220004	
OKKER - ND - 27 MK50	6123	FEATHERING PUMP			2 SDRs	QUE	P180 AVANTI	6120	PROPELLER CONTROL	580500018	FROZEN	20040908002	ON
F.28 MK0100	2230	AUTO THROTTLE SYS			20040917002		PC 12	3230	RELAY	9740926112	BURNED	20040831001	ON
28 MK0100	2562	UNDRIVITRACOUSTICEEACC			20040727002	QUE	PC 12 45	2140	TEMP CONTROL VALVE			3 SDRs	ON
28 MK0100 28 MK0100	2740 2820	STAB PROX SWITCH ACFT FUEL DIST SYS	864401		20041124004	QUE	PC 12 45 PC 12 45	2421	GENERATOR STARTER GENERATOR	23085024 23085024	OVERHAULED WOULD NOT ENGAGE	20040805004 20040726007	
28 MK0100	3070	HEATER			20041216002		PC 12 45	2434	BRUSH BLOCK ASSY	9789601091	WORNDIRTY	20040726007	
28 MK0100	3260	LANDING GEAR POSITION			2 SDRs	QUE	PC 12 45	2510	SEAT ASSY	9593001131		20040817005	ON
28 MK0100	3411 3418	PITOT PROBE	861DL		20040819010		PC 12 45	2710	MODULE, TERMINAL	9714231712	ORIGINAL	20040831014	
28 MK0100 28 MK0100	3810	ANGLE OF ATTACK POTABLE WATER SYS	OO ILJL		20041129013 2 SDRs	QUE	PC 12 45 PC 12 45	2720 2750	MODE CONTROL FLAP SYSTEM	065008617		20041122005	
28 MK0100	5311	FUSELAGEFRAMESTRIP		CRACK	20040826001	QUE	PC 12 45	2750	POWER DRIVE UNIT	9787320003		20040709009	ON
28 MK0100	5610		D20543406	CRACKED	20041124005	QUE	PC 12 45	2997	RELAY, HYDRAULIC	9740926112	FAILED	20041116001	ON
28 MK0100 28 MK0100	7200 7300	ENGINE ENGINE FUEL	TAY6501510	LEAKING	20041122009 20040827005	QUE	PC 12 45 PC 12 45	3221	SUPPORT NOSE OLEO	5531012326 5322012038	CRACKED FROZEN	20041201003 20041119004	ON
28 MK0100	7310	FUEL VENT LINE	A69351039	DISCONNECTED	20040803009		PC 12 45	3230	RELAY	9740926112		20040831016	
DUND BROS							PC 12 45	3230	WASHER, SPECIAL	5321012123	SHEARED PINS	20041108001	PN
BA 2C1 BA 2C1	5330 5510	BELLY SKIN HINGE BRACKET	S203307	CRACKING LOOSE	20041117001 20041116004	ONT	PC 12 45 PC 12 45	3242	BRAKE ASSY TIRE	03024400 85010		20040909009 20040811005	
-BA 2C1	5510	TRIM HINGE ASSY	F5131	CRACKED	20040913004		PC 12 45	3340	SWITCH	9736142510	INTERMITTENT OPE	20040713010	
AWKER SIDDEL	EY-UK						PC 12 45	3397	LANDING LIGHT WIRE	L40B16L41A16N	BROKEN	20040927005	ON
IS 748 2A IS 748 2A	1000	HOSE CLAMP GENERATOR	AGS6056	SERVICABLE	20040818006		PC 12 45 PC 12 45	3400 3412	WARNING FLAG	5829C000	DISLOCATED	20040709008	
IS 748 2A	2430	ALTERNATOR VOLTAGE			20041203004	PNR	PC 12 45	3418	TEMPERATURE CONTROL LEFT AOA VANE ASS.	9754421421		2 SDRs	PN
IS 748 2A	2432	BATTERY			20040803001	ONT	PC 12 45	3441	GPS.	0100121121		20040909008	ON
4S 748 2A	2612	FIRE WIRE	D237060	DAMAGED	20041112002	PAC	PC 12 45	5540	RUDDER	45005440	ATTACH HOLE WORN	20040730009	
IS 748 2A IS 748 2A	2750 3260	FLAP STARTER UNIT LEVERSWITCHOPERATING	EIC702322	SEVICABLE	20040913006 20040818005	ONT	PC 12 45 PC 12 45	6112 7400	DEICE BOOT IGNITION SYSTEM	4E305110		20040909010 20040910007	
IS 748 2A	5523	ELEVATOR TRIM TAB	1G3161	CRACKED	20040902007	PNR	PC 12 45	7800	LH EXHAUST STACK ASSY	5781012041	CRACK	20040713009	
AWKER SIDDEL							PC6 BH2	2710	BEARING	9408328011	SEIZED, LOOSE	2 SDRs	PN
H 125 800A JGHES	2750	WASHER / LATCH	SP10CCH614301		20040924002		PIPER PA23 250	2751	FLAP INDICATOR	1766903		20040709010	
69D	6210		369D21100517A	CRACKED SKIN	20041013006		PA23 250	7720	WRING	ANIEGO	CUT	20040709004	
69D 69D	6310	SPRAG ASSY M/R TRANSMISSION	369D25351SN58 369D25102SN006	BROKEN	20041112005	PAC	PA28 161 PA28 161	3213 5311	SCISSOR LINK BOLT FUSELAGE FRAME ASSY	AN522 6269504	SHEARED CRACKED/BUCKLED	20040902005	
369D	6510	OUTPUT SHAFT	369D25430	U/S	20040825013	PAC	PA30	2810	SCUPPER DRAIN		BLOCKED	20040930005	
369E	0000		369D27001	GOOD	20040729004	ATL	PA31	0000	BOLT	AN511A	FAILED	20041222012	

MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN		MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN
PA31 PA31 PA31 325	2710 3230 3230	CONTROL ROD DOWN LOCK BOLT ROD ASSY	40599003 AN546 4194902	CRACKED SEIZED STICKY	20040830014 20040831008 20041001002	QUE	:	engines	s	The second secon	Y			
PA31 350 PA31 750 PA31 750 PA31 750 PA31 750 PA31 750 PA31 750 PA31 750	2410 2435 2750 2820 3210 3220 3230 3230 3230 3230 5546 55730 55280 3210	ALTERNATOR STARTER FLAP MOTOR FLEXIBLE RUBBER TORQUE LINK TRUNION HYDRAULIC PUMP MLG RETRACTOR ARM	ALT8421R MHB4014 475212 8004804 CH20261 4027300 1213HBG310A 42042 4177100	STIZED POOR BURNT OUT CRACKED CRACKED CRACKED NO DAMAGE CRACKED BENT CRACKED BENT CRACKED	20041206004 20040920004 20040921002 20040921002 20041129012 20040172004 20040721002 20040721002 20040921003 20040921003 20040921003 20040921001 2 SDRs 20041220001 2 20040866009	PNR PNR PNR PNR ATL PNR ATL ONT ATL PNR PNR PNR PNR PNR PNR PNR ONT		ALLISON AE-3007A1/AE-3007A1/A E-3007A1/A 250 250-C20 250-C20 250-C20 250-C20 250-C20B 250-C20B 250-C20B 250-C20B 250-C20B 250-C20B 250-C20B 250-C20R 250-C20R	7230 7230 7261 7261 7250 7250 7310 7714 7160 7210 7230 7250 7532 0000	LP TURBINE HP COMPRESSOR NO 8 BEARING COMBUSTION OUTER CHECK VALVE TUBE TACH GENERATOR COMPRESSOR TURBINE ENGINE REDUCTI ADAPTER COUPLING TURBINE ASSY # BLEED VALVE TURBINE ASSEMBLY	6870992C 23074872 6875632 2514022A649 IONGEAR 230397911 230538160	FAILED DAMAGED BURNED CRACKED SERVICEABLE CRACKED UNSERVICEABLE STALLED SHEARED UNSERVICABLE FAILED	20041122006 20041122008 20040928015 20041129017 2004129908 2004163003 200410212 20041130005 20040705005 20040705005 20040720007	QUE PAC PAC QUE ONT ONT PAC PNR QUE ONT ATL
PA32RT 300T PA34 200T PA34 200T PA34 200T PA34 200T PA34 200T	2216 0000 3211 3222 5310 5711	CABLE ASSEMBLY TUBE ASSEMBLY ANCHOR NUT TUBE ASSY SKIN ASSY REAR SPAR FITTING	62701135 9572000 9572000 7861901 68621003	WORN OUT OF TOLERENCE NO DRAG TORQUE TOLERANCE OUT CHINGE SKIN THICK WORN	20040811007 20040831007 20040830002 20040901001 20041213001 20040720002	ONT		250-C28 250-C47B 250-C47B 250-C47B 501-D13D AVCO LYCOMING	7120 7240 7300 7321 7310	ENGINE LEG ASSEM COMBUSTION LINER ENGINE HARNESS A HYDROMECHANICAL BAR ASSY	206063106005 23064570 23065805 6654777	CRACKED CRACKED FAILED BROKEN	20040903002 6 SDRS 20040831002 20040726001 20040702003	ONT PAC ONT ATL
PA34 200T PA44 180 PA44 180 PA44 180 PA46 350P ROBINSON	6122 0000 0000 2740 7810	BEARING CABLE RUDDER ENGINE MOUNT RIGHT TRIM TAB COLLECTOR TANK	62701154 8936102 3839903 6402917	DESTROYED CHAFED CRACKED CRACKED CRACKED	20040921006 20041222011 20041224010 20040916004 20041216012	ONT QUE ONT ONT		HIO-360-D1A HO-360-C1A IO-360-B1E IO-360-L2A IO-360-L2A IO-540-L1C5	7414 8500 8550 7421 8550 8550	ROTOR SHAFT CARBURATOR CRANKCASE SPARK PLUG RECIPROCATING ENGINI OIL SUMP	M3548 1060301 10360BIE REM38E E 77517	BROCKEN FAILED CRACKED INSULATOR CRACK CASTING VOIDS	20041124003 20040706002 20041101004 20041222016 20041129004 20040901007	QUE
R22 BETA R22 BETA R44 R44 R44 R44	7322 7520 2421 2430 2510 2510	CARB HEAT CABLE FAN WHEEL COMMUTATOR BEARING RELAIS BATTERIE ANCHOR ASSY BUCKLE ASSEMBLY	KI153 C6284	FAILED FAILED OK CRACKED	20040706004 20040706005 20040702001 20041115009 20041008001 20040809003	PNR QUE PNR PNR		O-235-L2C O-235-L2C O-320 O-320-B2C O-320-D2J O-320-D2J	8520 8530 8530 7414 8520 8520	ENGINE ENGINE CYLINDER ASSEMBLY MAGNETO HYDRAULICTAPPET BODY RIGHT CRANKCASE	LW16730 SL32006WA21F S4LN204 LW72877 LW18402	CRACKED FAILED FAILED CRACKED CRACKED	20040825007 20040809001 20040709001 20040706003 20040831012 20041004002	PAC ONT ONT QUE ONT PAC
R44 R44 R44 ROCKWELL INTL 700	6320 7430 7714 3244	MAIN ROTOR TX IGNITION LOW RPM WARNING TIRE	C0066 A1661 A5696 AB3L6	OVERHEATED INOPERATIVE BLOWN	20040820004 20040809002 20041209015 20041209007	PNR		O-320-E2A O-320-E2D O-320-E2D O-320-E2D O-320-E3D	7322 8530 8530 8530 8500	FLOAT CONNECTING ROD BOLT CYLINDER ROCKER ARM RIGHT STACK ASSY	30804 SL78027 75868 74636 99044004	FAILED SEPARATED STUCK VALVE SPLIT CRACKED	20040804006 20040806004 20040713005 20040930004 20040713002	ONT ONT PAC PAC
SF340A 340B SCHWEIZER 269C 1	7314 3246 2300	HMU NOSE WHEEL TRIGGER SWITCH	6055T19P14 5006227A M880511104	MALFUNCTION	2 SDRs 20041119007 20041013009	ATL PNR QUE		O-320-H2AD O-320-H2AD O-360-A1D O-360-F1A6 O-540-E4C5	7414 7714 7120 8530 8520	CLAMP BLOCK TACHOMETER ENGINE MOUNT CYLINDER CRANKCASE	D11125025 590000	SERVICEABLE LEAKING BROKEN OVERHAULED CRACK	20040823007 20041215004 20041222005 20041220006 20041109001	PNR QUE PNR PNR QUE
269C 1 269C 1 SHORT&HARLAN SD3 60	2741 6320 D 5523	TRIMSWITCH CARRIER TRIM TAB BALANCE	A21810064603 269A5193001 SD3076011XA	STICKY CRACKED CRACKED	20041006001 20041102002 20041108008	ONT		O-540-F1B5 O-540-F1B5 O-540-F1B5 O-540-J3C5D	8500 8500 8520 8530	ENGINE GOVERNOR CONTROL ENGINE BODY HYDRAULIC TAPPET	D2781 72877	NEW CORRODED	20041231001 20041228001 2 SDRs 20041103003	PNR PNR PNR QUE
SIKORSKY S61N S61N S61N S61N S76A S76A S76A	6210 6320 6420 7600 0000 0000 5314	BLADE MAIN BEVEL GEAR HUB,ROTARY RUDDER ACTUATOR ROD ROTATING SCISSOR SUPPORT ARM, LOW KEEL, BEAM CONDUIT	6117020201 S613723054001 S611033003000 37C800410P101 7610708001104 7620202003101	FAILED SERVICEABLE STRIPPED CRRODED UNSERVICEABLE	20041124007 20041119005 20040916009 20040706001 20041224008 20041223004 20041201002	QUE QUE		O.540-J3C5D TIO-540-AK1A TIO-540-A2B TIO-540-G1A TIO-540-J2BD TIO-540-J2BD TIO-540-J2BD	8530 8540 7314 7414 8550 7314 7414 8530	PUSHROD HOUSING WASTEGATE SCREW MAGNETO OIL PRESSURE HOSE BYG DRIVEN FUEL PUMP MAGNETO CYLINDER ASS.	LW11485 470954001 LW25063 RG9080J4AM 1068291218 05K21108	SMALL PIN HOLE SEIZED SEPARATED LEAK LEAKING CRACKED/SEIZED SEPARATED	20040819008 20041216010 20040720006 20041119009 2 SDRs 2 SDRs 4 SDRs 3 SDRs	ONT PAC PAC QUE VAR VAR ATL
S76A S76A SLINGSBY T67C	6230 6520 7322	DUPLEX BEARING TAIL ROTOR SERVO CARB BUTTERFLY VALVE	SB1562101 7865005801112	SPALLED LEAKING UNDER INVESTIGATION	20040909006 20040914009	PAC		TIO-540-J2BD TIO-540-J2BD TIO-540-J2BD TIO-540-R2AD	8540 8560 8560 7810	HOSE TURBOCHARGER EXHAUST SEGMENT	UK 4091709001 LW16620	UNSERVICEABLE LEAKING BURNT	20041216009 20040831022 20040930001 20041119002	PAC PNR ATL ONT
SWEARINGEN SA226TC SA226TC SA226TC SA227AC	3230 3250 5610 2820	BELLCRANK ASSY LANDING GEAR STEERING S HEATED WINDSHIELD FUEL LINE	2719442004 8945681	WORN SHATTERED CRACKED	20041103004 20040705004 20041123009 20041126004	PNR PAC PNR ONT		BOMBARDIER RO 912 F3 914UL CFM INTERNATIO	8500 1000 DNAL	HOUSING ASSY, COMP ENGINE (RECIPROCATIN CLAMP	851116	THREAD DAMAGE	20041228002 20041122002 20040916008	PAC
SA227AC SA227AC	2910 5220	TUBE ASSEMBLY EMERGENCY EXIT	2781006143 2722181	CRACKED	20041116002 20040719002	ONT		CFM56-7B22 CURTISS WRIGH		TUBE - OIL SUPPLY	3381034050	LOOSE	20041216011	
SA227AC SA227AC	6111 8200	PROP SHAFT SEAL TUBE ASSEMBLY	31025751 2767030389	SEIZED CRACKED	20041019009 20040927006	ONT	:	982C9HE2 GARRETT	8530	ROCKER ARM BOLT	65678	BROKEN	20040715006	
SA227AC	8200	WATER INJECTION			20040709006	ONT		TFE731-2-2B TFE731-5BR TFE731-5BR-1C TPE331-10UA	7322 7932 7310 7334	MAIN FUEL CONTROL OIL SYSTEM FUEL LINE FUEL REGULATOR	307080022 30751301 8944416	FAILED DAMAGED LEAKING FUEL	20041222014 20040907006 20041119008 20041008002	PNR

MAKE/MODEL	JASC	PART NAME	PART NO.	PART CONDITION	SDR NO.	RGN		MAKE/MODEL	ASC P	ART NAME	PART NO. P	ART CONDITION	SDR NO.	RGN
TPE331-10UA-511G TPE331-10UA-511G TPE331-10UGR-514 TPE331-11U TPE331-11U	7250 7250 7310 7200 8011	HIGH SPEED PINION TURBINE WHEEL REAR ENG BEARING FUEL SHUT-OFF VALVE FCU STARTER GENERATOR*	8978015	WORN DAMAGED LEAKING FAILED	20040726003 20041202001 20041214005 20041209010 20041206007 20040920003	PNR PNR PNR ONT ONT	:	R-1340-S3H1-G R-1340-S3H1-G R-1340-S3H1-G R-1340-S3H1-G R-1340-S3H1-G	8530 8520 8520 8530 8530 8530	PISTON CAM CAM RING CYLINDER EXHAUST VALVE ENGINE	11768 11768 AE92181ER 71167	DAMAGED/CHIPPED WORN CRACKED DESTROYED FAILED	2004072100 2004100500 2004092800 2004091600 2004091600	11 QUE 12 QUE 17 QUE 15 QUE
TPE331-5-251K TPE331-6-252B GENERAL ELECT	7250 7310	ENGINE FUEL MANIFOLD	31024741	CRACKED	20040820003 20040707003	PNR		R-1340-59 R-2000-7M2 R-2000-7M2	8530 8500 8500	ROCKER ARM ACCELERATOR PUMP ENGINE	12973 81648	BROKEN	2004073000 2004071600 2004071600	6 ONT 7 NCR
CF34-3A2 CF34-3B1 CT58-140-1	7321 7200 7200	N1 AMPLIFIER ENGINE POWER TURBINE ASSY	4074T27G03 4006T87G09	BROKEN & DAMAGED	20041126006 20040929001 20040716006	QUE NCR PAC		R-2000-7M2 R-2800 R-985-AN-14B	8500 8510 8520	NOSE CASE PINION SHAFT CRANKSHAFT	260483 261280	OVERHAULED SHEARED FAILED	2004071600 2004081800 2004111600	9 PNR 13 PNR
CT7-5A2 INTERNATIONAL V2500-A1	7500 AERO 7230	POWERPLANT HPC 3-8 STAGE	CT75A2 6A7379	FAILED	20041021001	QUE	:	R-985-AN-14B R-985-AN-14B R-985-AN-14B	8520 8530 8530	IMPELLER AND SHA CYLINDER CYLINDER	19659 399353 47518	WORNLOOSE HEAD SEPARATION SEPERATED	2004092800 2004091300 2004090900	5 QUE
PRATT & WHITNI	EY-CAN		ORIGIS				:	R-985-AN-14B	8530	PISTON	27056	CRACKED	2004083001	2 PNR
JT15D-1A PT6A-112	7250 7314	ENGINE FUEL PUMP DRIVE	3022375	FAILED	4 SDRs 20041026009	VAR PAC		R-985-AN-14BM1 WASP CA3	8510	CYLINDER HEAD HO NOSE CASE ASSY	R985 519593	STUD BROKEN FAILED	2004080400 2004072200	6 PAC
PT6A-114A PT6A-20	7230 7200	SHROUD SEGMENT ENGINE	305309CL1	SHIFTED	20040818008 2 SDRs	ONT		WASP CA3 WASP CB3	8550 7420	MAIN OIL SCREEN LOW TENSION LEAD	125754 10878451	NEW BROKEN	2004072700 2004081800	4 ATL 9 PAC
PT6A-20 PT6A-25C	7310 7200	FUEL CONTROL UNIT ENGINE	25244394	FAILED	20040804011 20041117003	PAC	:	WASP CB3 ROLLS ROYCE -	8530	CYLINDER	356995	CRACKED	2004071200	
PT6A-27	2820	FUEL MANIFOLD	SEEBELOW	CLEANED & TESTED	20041129018	PNR	:	BR700-715A1-30	7200	ENGINE			2004092800	
PT6A-27 PT6A-28	7250 2421	ENGINE STARTER GENERATOR	PT6A27 23048018	FAILED	2 SDRS 20041130012	ATL. ONT		BR700-715A1-30 BR700-715A1-30		HP COMPRESSOR TURBINE/HPC		DAMAGED FAILURE	2004081300	
PT6A-28 PT6A-28	3425 7250	HORI SITUAT INDICATOR	066302710	OVERHEATED	20040730008 20040929008	QUE	:	DART 534-2 DART 534-2	7210 7921	TURBINE ENGINE R MATRIX	RK25198A	LEAKING	2004120200	6 PNR
PT6A-28	7261	ENGINE	PT6A28	FAILED	2 SDRS	VAR	:	ROLLS ROYCE -	UK					
PT6A-34 PT6A-34	7240 7250	COMBUSTOR SMALL ENGINE	3029248	CRACKED FAILED	20041221002 20040708007	QUE	:	RB211-535E4 TELEDYNE CONT	7220 INENTA	FAIRING NOSE CON	UL16113	FAILED	2004080500	1 QUE
PT6A-34 PT6A-42	7810 7920	EXHAUST DUCT OIL FILTER (PUROFLOW)	P1010	CRACKED USED	20041215001	ONT	:	IO-360-C IO-360-C	8011 8520	BEVEL GEAR CRANKCASE	632617	DESTROYED CRACKED	2004090901 2004073000	
PT6A-50 PT6A-50	6120 7200	ENGINE		FAILED FAILED	20040903003	ATL	:	IO-470 IO-520-A	7120	BOLT LOCKING TAB	08515591	MISSING	2004072200	7 PAC
PT6A-50	7210	FUEL CONTROL UNIT ENGINE		FAILED	20040713006 20040819009	ATL	:	IO-520-D	7931 7112	OIL GAUGE ROD CYLINDER	6320622 TIST712ACA	TOO LONG SCRAP	2004101900 2004102600	8 ONT
PT6A-65AR PT6A-67B	7210 7200	BOLT ENGINE	MS949034	FRACTURED	2 SDRs 20041215007	PNR	:	IO-520-D IO-520-D	7420 8500	MAGNETO ENGINE	6310 IO520D	ARCING	2004100101 2004101700	
PT6A-67B PT6A-67B	7210 7314	CHIP DETECTOR HIGH PRESSURE FU	304544901 8256015	DAMAGED METAL CONTAMINATE	20041101010	PNR	:	IO-520-D IO-520-D	8530 8530	CYLINDER ASSEMBL RECIPROCATING EN	CNF71ER 649199P10A1	CRACKED CRACKED	2004092100	5 PNR
PT6A-67B	7322	FUEL CONTROL UNIT	8063041	METAL CONTAMINATE	20041020004	PNR	:	IO-520-F	6114	HUB SEAL		LEAKING	2004083000	9 PNR
PT6A-67D PT6A-67D	7200 7210	ENGINE 1ST CARRIER MACH	MS949034	FAILED BOLT HEAD	2 SDRs 20040727003	VAR PNR	:	IO-520-F IO-520-F	7322 7421	METERING UNIT SPARK PLUG	629390A8 URHB32E	LEAKING BROKEN	2004122000	5 PAC 2 ONT
PT6A-67D PT6A-67D	7230 7250	CT BLADE POWER SECTION	311899101 310803101	SHEARED	20040722004 2 SDRs	PNR	:	IO-520-F IO-520-F	8520 8520	CONNECTING ROD CRANKCASE	654101A7R	UNSERVICEABLE	3 SDRs 2004080600	PNR 6 PNR
PT6A-67D PT6T-3	7321 7200		8063005B	BINDING FAILED	20041110013 20040831005	PAC	:	IO-520-F IO-520-F	8520 8530	PISTON ENGINE		LOOSE & SPINNING	2004112000	1 PNR
PT6T-3	7250	PC AIRLINE	3017393	BROKEN	20040928016	PAC	:	10-550-F	7931	PUSH ROD TUBE OIL GAUGE ROD	537296 6320622	CRACKED AND BENT TOO LONG	2004092400 2004101900	7 PAC
PT6T-3 PT6T-6	7250 7230	TURBINE SECTION COMPRESSOR TURBINE	3024211	FAILED CRACKED	20040908005 20040928010	ONT	:	IO-550-F IO-550-F	8530 8550	CYLINDER ADJUSTING SCREW	ACE631397 642335	CRACKED/LEAKING WORN	2004101800	
PW121 PW121	6110 7250		310703601	CRACKED FAILED	20040928011 2 SDRs	QUE		O-200-A O-200-A	8530 8530	EXHAUST VALVE EXHAUST VALVES	646612 631619	SCRAP DEFORMED	2004083000	1 ONT
PW123B	7200	NO 2 ENGINE		TAILED	20040914001	NCR	:	O-300-A	7414	IMPULSE SPRING C	M3590	BROKEN	2004072300	5 ONT
PW123D PW124B	7200 6120	ENGINE ENGINE			20041026001 20041122014	NCR QUE	:	O-300-D TSIO-360-FB	7322 7310	CARBURETOR ANGLE FITTING	MA3SPA	FAILED CRACKED	2004081900 2004101300	7 PNR
PW124B PW125B	7260 7200	ENGINE ENGINE			20041124011 20041209012	QUE	:	TSIO-470-B TSIO-520-AE	8530 8520	INTAKE/EXHAUST P CAM SHAFT	6524518 643045	BROKEN SHEARED	2004083001	
PW150A PW150A	7200 7931	ENGINE NO. 1 ENGINE			20041020009 20040816002	QUE	:	TSIO-520-E TSIO-520-N	8530 8530	CYLINDER CRANKCASE	AEC631397ST712B 643207		2004092300	2 QUE
PW206B	7722	ENG. EGT/TIT IND			20041022004	QUE		TURBOMECA			043207			
PW206C PW305B	7200 7310	ENGINE ENGINE			20041026002 20041222019	QUE	:	ARRIEL 1B ARRIEL 1B	7230 7310	MO 2/3 PIPE-SUPPLY, L/H	0301007720	UNSERVICEABLE CRACKED	20041110002	QUE 4 QUE
PW306B PW308C	7334 8012	FUEL FLOW TRANSM AIR START VALVE			20040923005 20041222015	QUE	:	ARRIEL 1B ARRIEL 1B	7320 7322	FUEL CONTROL FUEL CONTROL	0164448430	FAILED UNSERVICEABLE	20041105006	
PW530A PW530A	7200 7310	ENGINE	31J251302	LEAKING	20041209013	QUE	:	ARRIEL 1B ARRIEL 1B	7532 7714	BLEED VALVE TACH BOX	9550158260	FAILED	2 SDRs	QUE
PW545A	7200	ENGINE (TURBINE)	310231302	LEANING	20041008003	QUE	:	ARRIEL 1B	7931	ENG OIL PRESS SE	0177555150 704A37642043	FAILED FAILED	2004080400/	5 QUE
PW545B PRATT & WHITNE	7200 Y-USA	ENGINE			20041117004	QUE	:	ARRIEL 1D1 ARRIEL 2B	7313 7210	START INJECTORS RECEPTACLE	0283317500 9520011653	GOOD	2004080500	
JT8D-17 JT8D-7B	7932 7250	OIL QTY INDICATOR TURBINE SECTION	10607225 JT8D7BQN	UNRELIABLE DAMAGED	20041214007 20040910005	ONT	:	ARRIEL 2B ARRIUS 2F	7712 7310	TORQUEMETER REFE BOOST FUEL PUMP	P94C16612	LOOSE CONTAMINATED	2004091300:	2 ONT
JT8D-9A	4930	APU	UIDDIDGIN	DAMINGEL	20041007001	PAC		ARRIUS 2F	7310	L/H FUEL MANIFOLD	0319738340	CHAFED	2004081200	
JT8D-9A JT8D-9A	7200 7532	ENGINE (TURBINE) PRBC		LOOSE FITTING	20041117005 20041214001	ATL								
R-1340-AN-1	8530	ENGINE	399359	CRACKED	20040915005	ONT								

AEROPRODUCTS A6441FN-606	S 6122	PROPELLER			20040720005	PNR
DOWTY ROTOL	Olaz					
R389/4-123-F/25	6114	HUB	660710840	CRACKED	20040805015	QUE
HAMILTON STAN	IDARD					
14SF-7	6111	BLADE AND PIN ASSY	SFA13M1R0AD	CORRODED	20040901006	ONT
14SF-7	6112	PROPELLER BLADE	SFA13MIROADE	BROKEN BLADE	20041115002	NCR
54H60-117	6100	PROP VALVE HOUSING	582855		20041018007	ONT
HARTZELL						
HC-B3TN-5M	6111	BLADE CLAMP	83867	CRACKED	20041110018	PAC
HC-E2YL-2BS	6114	HUB	D2483	CORRODED	2 SDRs	PAC
HC-E4A-3D	6112	DEICE BOOT	4E305110		20040927004	ONT
HC-82VF-1DB	6114	PROPELLER	HC8VF1DB	DOWELS MISSING	20040708004	PAC
MCCAULEY						
D2AF34C305	6114	HUB	D4190305	U/S	20041019004	PAC
D2A34C58	6111	RETENTION NUT	C4902	CRACKED	20041222010	ONT
D2A34C67	6114	PROPELLER HUB /	D613276C0	CORRODED	8 SDRs	PAC
3AF32C87-NR	6111	PROP DE-ICE PAD	P5855BSW	TEAR	20040930006	QUE

equipment

AVIALL						
BS2166 DMELT	2432 2562	NIL/UNKNOWN BATTERY PACK	BS2173	LEAKING	20040909011 20040804012	PNR PNR
AVIONIC PROD U384U BARBER COLEM	2497	NEXUS PLUG-HEADS	U384U	NEW	20040923008	NCR
	2160	HARDWARE/TRANSISTOR	J4RF284001E2029	WRONG/SHORTED	20041102005	PNR
	2562	ELT	ELT200	ACTIVATED	20041029001	ATL
	3400	NAV CONTROL HEAD	6226521016	BULB SHORTED	20041015006	PNR
ELT6 ELT81	2510 2561	BATTERY BATTERY PACK	BS2173 BS2173	CORRODED	20041021002 2 SDRs	PNR
	3244	TAILWHEELTIRE	2802504	UNCURED	20040827004	PAC
WOODWARD GOV B210761	6122	PILOT VALVE, FLY	210332210316	CORRODED	20041209011	PNR

LEGEND

Joint Aircraft System Code number defining assembly/system/component JASC SDR NO. TCA assigned SDR control number - please quote in any correspondence or inquiries RGN TCA region of SDR submitter:

> PAC = Pacific, PNR - Prairie Northern, ONT - Ontario, QUE = Quebec, NCR = Ottawa (HQ), ATL = Atlantic, VAR = more than one Region

headquarters headquarters

Atlantic	
Prairie and Northern	feedback (TP 6980E) is published quarterly by the Continuing Airworthiness Division of Transport Canada, informing the aviation community of reported day-to-day problems that affect aircraft airworthiness in Canada.
OntarioQuebec	The articles contained in feedback are derived from Service Difficulty Reports (SDRs) submitted by Aircraft Maintenance Engineers (AMEs), owners, operators and other sources.
Pacific	For additional information concerning feedback or the Service Difficulty Reporting Program, contact your nearest Transport Canada Centre.

Where to find us in cyberspace

http://www.tc.gc.ca/civilaviation/certification/menu.htm